

UNIT INFORMATION SHEETS FOR NS 5098 AT SHOP SCY ON 06/01/17 PAGE 1

TASKS AND INFO LISTED ARE VALID THROUGH END OF SHOPPING COMMENCING ON DATE SHOWN AT TOP OF PAGE (ML949A)

CRITICAL UNIT DATA			
	LAST DONE	SHOP	NEXT DUE
# LUBE	11/13/16	INM	12/27/16
# 3 MONTH - MAINT EXPEDITED	11/13/16	INM	05/13/17
# 6 MONTH	11/13/16	INM	07/04/17
- METER	11/13/16	INM	01/04/18
- 12 MONTH	11/13/16	INM	01/04/18
- 24/36/48/60	05/09/14	SPE	01/04/18
# EVENT RECORDER	11/13/16	INM	05/13/17
- EPA 1 YEAR	11/13/16	INM	11/15/17
# EPA 2 YEAR	02/09/15	SPE	02/13/17
- EPA 3 YEAR	02/09/15	SPE	02/06/18
# EPA 4 YEAR	02/22/13	SPE	03/04/17
- EPA 6 YEAR	02/09/15	SPE	02/24/21
- EPA 12 YEAR	03/04/09	JUN	04/05/21
# MID-LIFE TUNE UP	02/25/09	JUN	12/04/15
- OVERHAUL	02/25/09	JUN	12/20/21
# TRUCK CHANGE	08/07/03	JUN	05/29/15
- RETRO REFLECTIVE	05/16/15	SPE	06/11/25
# BATTERY SET CHANGE	04/10/06	SPE	01/27/17

AIR COMP: ? AIR DRYER: ? OIL CHG: 02/24/98

RI: EPA: 0 RAILVIEW: N APU: K99

CAB SGNL: N TM TYPE: 723D77,40H BEARING TYPE: HYATT RMT CTL: N

Left side AEI tag(s) on unit is(are) defective.  
Replace transponder (AEI) tag(s) during this shopping.

EMISSION CRITICAL PARTS

ENGINE LABEL:	◀ECT01-ECTK0645E01
LOCO LABEL:	◀ECT01-ECTK0645E01
EPA COMPLIANCE:	-0-TIER 0
EPA REGULATION:	-A-92
Turbo/GE LP Turbo	]N/A-NOT APPLICABLE
GE HP/EMD HPC Turbo	]N/A-NOT APPLICABLE
Injector/Pump	-M-EMD MUI
Injector/Nozzle ID	]316-376316 EMD 8478045 8,12,
Master Connecting Rod PA	]N/A-NOT APPLICABLE
Art Connecting Rod PA	]N/A-N/A
Power Assembly	]N/A-NOT APPLICABLE
Short Power Assembly (PA)	-583979-JUN MUI 645E TIER 0
Air to Air Intercooler	]N/A-NOT APPLICABLE
Air to Water Intercooler	]N/A-NOT APPLICABLE
Camshaft (Left End)	]N/A-NOT APPLICABLE
Camshaft (Left Mid):	]N/A-NOT APPLICABLE
Camshaft (Right End)	]N/A-NOT APPLICABLE
Camshaft (Right Mid):	]N/A-NOT APPLICABLE
Piston Ring Kit	]N/A-NOT APPLICABLE
EGU/ECU/ECM/Governor	321957-EMD 8482396 16-645E
LEFT CAM POS 1:	]N/A-NOT APPLICABLE
LEFT CAM POS 2:	]N/A-NOT APPLICABLE
LEFT CAM POS 3:	]N/A-NOT APPLICABLE
LEFT CAM POS 4:	]N/A-NOT APPLICABLE
LEFT CAM POS 5:	]N/A-NOT APPLICABLE
LEFT CAM POS 6:	]N/A-NOT APPLICABLE
LEFT CAM POS 7:	]N/A-NOT APPLICABLE
LEFT CAM POS 8:	]N/A-NOT APPLICABLE
LEFT JOURNAL POS 1:	]N/A-NOT APPLICABLE
LEFT JOURNAL POS 2:	]N/A-NOT APPLICABLE
LEFT JOURNAL POS 3:	]N/A-NOT APPLICABLE
LEFT JOURNAL POS 4:	]N/A-NOT APPLICABLE
LEFT JOURNAL POS 5:	]N/A-NOT APPLICABLE
LEFT JOURNAL POS 6:	]N/A-NOT APPLICABLE
LEFT JOURNAL POS 7:	]N/A-NOT APPLICABLE
LEFT JOURNAL POS 8:	]N/A-NOT APPLICABLE
LEFT JOURNAL POS 9:	]N/A-NOT APPLICABLE
RIGHT CAM POS 1:	]N/A-NOT APPLICABLE
RIGHT CAM POS 2:	]N/A-NOT APPLICABLE
RIGHT CAM POS 3:	]N/A-NOT APPLICABLE
RIGHT CAM POS 4:	]N/A-NOT APPLICABLE
RIGHT CAM POS 5:	]N/A-NOT APPLICABLE
RIGHT CAM POS 6:	]N/A-NOT APPLICABLE
RIGHT CAM POS 7:	]N/A-NOT APPLICABLE
RIGHT CAM POS 8:	]N/A-NOT APPLICABLE
RIGHT JOURNAL POS 1:	]N/A-NOT APPLICABLE
RIGHT JOURNAL POS 2:	]N/A-NOT APPLICABLE
RIGHT JOURNAL POS 3:	]N/A-NOT APPLICABLE
RIGHT JOURNAL POS 4:	]N/A-NOT APPLICABLE
RIGHT JOURNAL POS 5:	]N/A-NOT APPLICABLE
RIGHT JOURNAL POS 6:	]N/A-NOT APPLICABLE
RIGHT JOURNAL POS 7:	]N/A-NOT APPLICABLE
RIGHT JOURNAL POS 8:	]N/A-NOT APPLICABLE
RIGHT JOURNAL POS 9:	]N/A-NOT APPLICABLE

UNIT INFORMATION SHEETS FOR NS 5098 AT SHOP SCY ON 06/01/17 PAGE 2

TASKS AND INFO LISTED ARE VALID THROUGH END OF (ML949A)  
 SHOPPING COMMENCING ON DATE SHOWN AT TOP OF PAGE

COMPONENT CHANGE HISTORY

DATE DESCRIPTION POS  
 HAS NO COMPONENT CHANGEOUT HISTORY

UNSCHEDULED SHOPPING HISTORY

HAS NO UNSCHEDULED SHOPPING HISTORY

LATEST WHEEL DATA

AXLE	LRT	LFH	LFT	RRT	RFH	RFT
1	2 12/16	1 3/16	1 7/16	2 11/16	1 5/16	1 4/16
2	1 8/16	1 5/16	1 6/16	1 7/16	1 6/16	1 3/16
3	1 4/16	1 6/16	1 3/16	1 3/16	1 6/16	1 5/16
4	1 10/16	1 3/16	1 4/16	1 10/16	1 3/16	1 4/16

KIPS READING > 75

POS PEAK DATE  
 HAS NO WHEEL DATA AVAILABLE

OPEN ACCIDENTS

HAS NO OPEN ACCIDENTS

TROUBLE HISTORY

ME 05-16-2017 STORE UNIT  
 UNIT TROUBLE COMMENTS:  
 ROUTE TO SCX FOR STORAGE. CONTACT SOC UPON ARRIVAL AT SHOP TO HAVE UNIT  
 PLACED IN STORED STATUS.  
 RESOLVED: BY:

TT 12-19-2016 CREW CAB TROUBLE  
 UNIT TROUBLE COMMENTS:  
 LCDI CAT: CREW CAB PROBLEM , DEF: DOOR,OTHER,  
 MECH DEPT ASSESSMENT COMMENTS:  
 DOOR WHAT? OLD TROUBLE. FOUND DOOR HANDLE WAS LOOSE  
 MECH DEPT RESOLUTION COMMENTS:  
 INSTALLED NEW SCREWS TO TIGHTEN DOOR HANDLE  
 RESOLVED: 04-02-2017 22:34 BY: ICEFU

LAB ANALYSIS HISTORY

	PB	CU	FE	AL	SI	CR	B	ZN	V100	%F	HD	PPI	OS
05-27-2017									15.3	220	20	44	29
03-30-2017	2	14	13	2	3	3	1		15.3	216	16	45	29

UNIT INFORMATION SHEETS FOR NS 5098 AT SHOP SCY ON 06/01/17 PAGE 3

TASKS AND INFO LISTED ARE VALID THROUGH END OF (ML949A)  
SHOPPING COMMENCING ON DATE SHOWN AT TOP OF PAGE

12-15-2016 3 12 9 2 3 3 2 15.3 222 13 45 26

---

NOTICES DUE

MDH MO 6653 Dash-2 Locomotive Cab Replacement

MDH MO 6821 Remove Exterior Toilet Dump Slide Valve

MDH MO 6865 K9 and K9.9 APU 240 VAC Distribution Upgrade

---

UNRESOLVED LAB DATA

05-27-2017: ADD 0.75 GAL OR 1 POUCHES OR 6 BAGS OF BORON TREATMENT.  
SYSTEM: COOLING