

UNIT INFORMATION SHEETS FOR NS 5119 AT SHOP SCY ON 02/11/16 PAGE 1

TASKS AND INFO LISTED ARE VALID THROUGH END OF SHOPPING COMMENCING ON DATE SHOWN AT TOP OF PAGE (ML949A)

CRITICAL UNIT DATA			
	LAST DONE	SHOP	NEXT DUE
# LUBE	12/13/15	MAC	01/26/16
- 3 MONTH - MAINT EXPEDITED	12/14/15	MAC	04/14/16
- 6 MONTH	12/14/15	MAC	07/06/16
- METER	06/04/15	MAC	07/06/16
- 12 MONTH	06/04/15	MAC	07/06/16
- 24/36/48/60	06/04/15	MAC	07/12/18
- EVENT RECORDER	12/14/15	MAC	04/14/16
# MID-LIFE TUNE UP	04/07/08	JUN	07/03/14
# OVERHAUL	11/29/01	JUN	03/12/14
# TRUCK CHANGE	08/25/04	JUN	12/04/15
- RETRO REFLECTIVE	06/04/15	MAC	06/30/25
# BATTERY SET CHANGE	08/25/04	JUN	12/01/14

AIR COMP: 11/27/01 AIR DRYER: ? OIL CHG: 02/27/15

RI: 100 EPA: N RAILVIEW: N APU: ?

CAB SGNL: N TM TYPE: 723D77,40H BEARING TYPE: HYATT RMT CTL: N

COMPONENT CHANGE HISTORY			
DATE	DESCRIPTION		POS
12-13-2015	LUBRICANT, SODIUM BASE 1LB		ALL
12-13-2015	LUBRICANT, SODIUM BASE 1LB		ALL
12-13-2015	FILTER, LUBE OIL		N/A
12-13-2015	GASKET COVER LUBE OIL FILTER MICHIANA		N/A
12-13-2015	ELEMENT, FIBERGLASS BAGGY TYPE FILTER		N/A
12-13-2015	GASKET COVER FUEL OIL FILTER		N/A
12-13-2015	FILTER, LUBE OIL		N/A
12-13-2015	ELEMENT, SPIN ON FUEL FILTER		N/A
12-13-2015	ELEMENT, AIR COMPRESSOR FILTER, ROUND		N/A
12-13-2015	FILTER, APU & AIR COMP LUBE OIL		N/A
12-13-2015	NOZZLE, SANDING(HOSE/BOOT/SANDER)		ALL
12-13-2015	SHOE, COMPOSITE BRAKE 2IN		ALL
12-13-2015	SHOE, COMPOSITE BRAKE 2IN		ALL
10-28-2015	SHOE, COMPOSITE BRAKE 2IN		L01
10-27-2015	CONTROLLER, DB/THROTTLE		N/A
09-06-2015	MOTOR, REVERSER, TRANSFER/SWITCH/MB/RV		N/A
09-06-2015	POMER ASSEMBLY, SHORT W/O ROD 645E Tier0		002
09-05-2015	LUBRICANT, SODIUM BASE 1LB		ALL
09-05-2015	LUBRICANT, SODIUM BASE 1LB		ALL
09-05-2015	GASKET COVER FUEL OIL FILTER		N/A
09-05-2015	FILTER, LUBE OIL		N/A
09-05-2015	ELEMENT, SPIN ON FUEL FILTER		N/A
09-05-2015	BRUSH, TRACTION MOTOR SD60 EMD 9582217		ALL
09-05-2015	BRUSH, GRADE AG137		ALL
09-05-2015	BRUSH, TRACTION MOTOR SD60 EMD 9582217		ALL

UNIT INFORMATION SHEETS FOR NS 5119 AT SHOP SCY ON 02/11/16 PAGE 2

TASKS AND INFO LISTED ARE VALID THROUGH END OF SHOPPING COMMENCING ON DATE SHOWN AT TOP OF PAGE (ML949A)

09-05-2015	BRUSH, GRADE AG137	ALL
09-05-2015	SHOE, COMPOSITE BRAKE 2IN	ALL
09-05-2015	SHOE, COMPOSITE BRAKE 2IN	ALL
09-04-2015	NOZZLE, SANDING(HOSE/BOOT/SANDER)	ALL
09-04-2015	BOTTLE, PLASTIC 4 OZ, 525 IN A CASE	N/A

UNSCCHEDULED SHOPPING HISTORY

09-27-2015 MAC LCDI CAT: HORN OR BELL, DEF: BELL,DOES NOT RING,

LATEST WHEEL DATA

AXLE	LRT	LFH	LFT	RRT	RFH	RFT
1	2 10/16	1 1/16	1 2/16	2 9/16	1 1/16	1 2/16
2	2 16/16	1 4/16	1 5/16	2 14/16	1 5/16	1 4/16
3	3 1/16	1 3/16	1 5/16	3 0/16	1 2/16	1 6/16
4	1 4/16	1 2/16	1 1/16	1 4/16	1 3/16	1 3/16

KIPS READING > 75

POS PEAK DATE
HAS NO WHEEL DATA AVAILABLE

OPEN ACCIDENTS

HAS NO OPEN ACCIDENTS

TROUBLE HISTORY

TT 12-16-2015 STORE UNIT

UNIT TROUBLE COMMENTS:
CONTACT SOC UPON ARRIVAL AT SHOP TO BE PLACED IN STORED STATUS. UNIT SHOULD BE STORED AT THE FOLLOWING LOCATION: SCX
RESOLVED: BY:

TT 10-22-2015 CREW CAB TROUBLE

UNIT TROUBLE COMMENTS:
THROTTLE HANDLE BROKE INSIDE OF THE ENGINEER CONTROL STAND
MECH DEPT ASSESSMENT COMMENTS:
THROTTLE CHUCK NEEDS TO BE REPLACED.
MECH DEPT RESOLUTION COMMENTS:
REPLACED THROTTLE CHUCK. LOAD TESTED UNIT INSHOP. UNIT LOAD TESTED WITH NO PROBLEMS,
COMPONENT(S) USED:
CONTROLLER, CONTROL STAND
RESOLVED: 10-27-2015 19:30 BY: AYTAA

TT 09-27-2015 HORN / BELL TROUBLE

UNIT TROUBLE COMMENTS:
LCDI CAT: HORN OR BELL, DEF: BELL, BELL WILL NOT RING

UNIT INFORMATION SHEETS FOR NS 5119 AT SHOP SCY ON 02/11/16 PAGE 3

TASKS AND INFO LISTED ARE VALID THROUGH END OF (ML949A)
SHOPPING COMMENCING ON DATE SHOWN AT TOP OF PAGE

MECH DEPT ASSESSMENT COMMENTS:

BELL WOULD NOT RING

MECH DEPT RESOLUTION COMMENTS:

LUBRICATED BELL. TESTED BELL MULTIPLE TIMES. RINGS OK.

RESOLVED: 10-27-2015 19:46 BY: AYTAA

ME 09-13-2015 ENGINE TROUBLE

UNIT TROUBLE COMMENTS:

LCDI CAT: ENGINE ROOM, DEF: ENGINE OIL AND FUEL,GOVENOR BUTTON TRIPPED , OTHER,

MECH DEPT ASSESSMENT COMMENTS:

FOUND LOCOMOTIVE LOW IN OIL

MECH DEPT RESOLUTION COMMENTS:

ADD 150 + GALLONS TO ENGINE LOAD TESTED FOR 30 MIN C/O OK

RESOLVED: 10-28-2015 06:41 BY: MA02A

ME 09-13-2015 DAILY SERVICING / SUPPLIES L

UNIT TROUBLE COMMENTS:

LCDI CAT: BRAKE RIGGING, DEF: EXCESSIVE PISTON TRAVEL,OTHER,

MECH DEPT ASSESSMENT COMMENTS:

CHANGED BRAKE SHOES AND ADJUSTED PISTON TRAVEL

MECH DEPT RESOLUTION COMMENTS:

OK

COMPONENT(S) USED:

TRUCK,BRAKE SHOE

RESOLVED: 10-28-2015 06:39 BY: MA02A

TT 09-02-2015 NOT LOADING PROPERLY/WSA/TRANS

UNIT TROUBLE COMMENTS:

LCDI CAT: LOADING TROUBLE , DEF: ONLY LOADS 1 DIRECTION,OTHER, ONLY LOADS LONG HOOD DIRECTION

MECH DEPT ASSESSMENT COMMENTS:

ONLY LOADS 1 DIRECTION,OTHER, ONLY LOADS LONG HOOD DIRECTION

MECH DEPT RESOLUTION COMMENTS:

LOADED UNIT IN BOTH DIRECTIONS UP TO 500 AMPS WITH NO TROUBLE AND

LOADTESTED OK.

RESOLVED: 09-04-2015 10:35 BY: MBCZF

TT 08-31-2015 LOSING COOLING WATER / TLWD/CO

UNIT TROUBLE COMMENTS:

RPTD LOW WATER LEVEL.TA.(WJ)

MECH DEPT ASSESSMENT COMMENTS:

(INMAN LOCOMOTIVE)PULLED AIR BOX COVER FOR P.A. #7 DURING INITIAL INSPECTION AND WATER/OIL MIXTURE POURED OUT HEAVILY, PROBABLY A TOTAL OF 5 GALLONS. BELIEVE THAT AIR BOX DRAIN FOR

MECH DEPT RESOLUTION COMMENTS:

RENEWED #2 P.A. .PRESSURE TESTED AND FOUND NO FURTHER TROUBLE RELATED TO THE ABOVE TROUBLE.

COMPONENT(S) USED:

PA (POWER ASSEMBLY)

RESOLVED: 09-06-2015 05:24 BY: MBZ4U

UNIT INFORMATION SHEETS FOR NS 5119 AT SHOP SCY ON 02/11/16 PAGE 4

TASKS AND INFO LISTED ARE VALID THROUGH END OF (ML949A)
 SHOPPING COMMENCING ON DATE SHOWN AT TOP OF PAGE

TT 08-10-2015 DYNAMIC BRAKE TROUBLE (LDI 1-3)

UNIT TROUBLE COMMENTS:

LCDI CAT: DYNAMIC BRAKE, DEF: LOADING TROUBLE,HEAVY LOADING,

MECH DEPT ASSESSMENT COMMENTS:

CHECKED LOADING IN BOTH DIRECTIONS. FOUND UNIT WILL NOT LOAD IN ONE DIRECTION. FOUND B/O REVERSER MOTOR. CHANGED REVERSER MOTOR.

MECH DEPT RESOLUTION COMMENTS:

CHECK LOCO FOR HEAVY LOADING AFTER REVERSER MOTOR CHANGE. LOCO LOADS CORRECTLY AT THE CORRECT AMPS. CHECKED AMPS IN DYNAMIC BRAKE AND AMPERAGE IS CORRECT. LOAD BOXED UNIT AND VOLTA

COMPONENT(S) USED:

MOTOR,REVERSER

RESOLVED: 09-06-2015 06:00 BY: LC3UY

MOTOR,REVERSER

LAB ANALYSIS HISTORY

	PB	CU	FE	AL	SI	CR	B	ZN	V100	%F	HD	PPI	OS
01-11-2016	2	11	17	2	9	6	9	3	13.3	221	18	35	26
12-13-2015		8	9	2	4	3	11	2	13.3	223	19	37	24
10-28-2015	2	15	7	2	3	2	15	4	14.3	221	15	30	22
09-04-2015	9	23	22	3	25	5	108	6	15.2	220	21	45	27

NOTICES DUE

MDH MO 6653 Dash-2 Locomotive Cab Replacement

MDH MO 6727 Dash 2 Battery Saver ZTR

MDH MO 6821 Remove Exterior Toilet Dump Slide Valve

MDH MO 6825 Replace toilet top

MDH WR 221 Replace Toilet Floor Flange Seal

MDH WR 222 Apply Toilet Chemical Sticker to Toilet

UNRESOLVED LAB DATA

HAS NO UNRESOLVED LABS