

UNIT INFORMATION SHEETS FOR NS 5141 AT SHOP SCY ON 08/01/16 PAGE 1

TASKS AND INFO LISTED ARE VALID THROUGH END OF SHOPPING COMMENCING ON DATE SHOWN AT TOP OF PAGE (ML949A)

CRITICAL UNIT DATA			
	LAST DONE	SHOP	NEXT DUE
# OIL/WTR SAMP	05/03/16	SHE	05/17/16
# LUBE	04/23/16	SHE	05/22/16
# 3 MONTH - MAINT EXPEDITED	02/24/16	SHE	07/27/16
# 6 MONTH	11/17/15	SPE	07/27/16
# METER	05/17/15	SPE	07/27/16
# 12 MONTH	05/17/15	SPE	07/27/16
# 24/36/48/60	11/06/13	CHA	07/27/16
# EVENT RECORDER	02/24/16	SHE	07/27/16
# EPA 1 YEAR	05/17/15	SPE	05/18/16
# EPA 3 YEAR	05/08/13	JUN	05/15/16
- MID-LIFE TUNE UP	05/08/13	JUN	05/24/19
- OVERHAUL	05/08/13	JUN	06/09/25
# TRUCK CHANGE	09/11/03	JUN	09/16/15
- RETRO REFLECTIVE	02/24/13	JUN	03/23/23
- BATTERY SET CHANGE	11/10/13	CHA	12/07/23

AIR COMP: ? AIR DRYER: ? OIL CHG: 02/02/12

RI: EPA: A RAILVIEW: N APU: ?

CAB SGNL: N TM TYPE: 723D77,40H BEARING TYPE: HYATT RMT CTL: N

COMPONENT CHANGE HISTORY		
DATE	DESCRIPTION	POS
02-23-2016	LUBRICANT, SODIUM BASE 1LB	ALL
02-23-2016	LUBRICANT, SODIUM BASE 1LB	ALL
02-23-2016	GASKET COVER FUEL OIL FILTER	N/A
02-23-2016	FILTER, LUBE OIL	N/A
02-23-2016	ELEMENT, SPIN ON FUEL FILTER	N/A
02-23-2016	LOCO SAMPLE BOTTLE W/ LID, PLASTIC	N/A
02-22-2016	SHOE, COMPOSITE BRAKE 2IN	ALL
02-22-2016	SHOE, COMPOSITE BRAKE 2IN	ALL
02-21-2016	NOZZLE, SANDING(HOSE/BOOT/SANDER)	ALL

UNSCCHEDULED SHOPPING HISTORY

05-18-2016 SHE IS

LATEST WHEEL DATA

AXLE	LRT	LFH	LFT	RRT	RFH	RFT
1	1 5/16	1 5/16	1 5/16	1 4/16	1 7/16	1 3/16
2	1 7/16	1 5/16	1 4/16	1 7/16	1 5/16	1 5/16
3	2 0/16	1 2/16	1 4/16	2 0/16	1 3/16	1 5/16
4	2 12/16	1 3/16	1 6/16	2 11/16	1 3/16	1 6/16

KIPS READING > 75

POS PEAK DATE
HAS NO WHEEL DATA AVAILABLE

UNIT INFORMATION SHEETS FOR NS 5141 AT SHOP SCY ON 08/01/16 PAGE 2

TASKS AND INFO LISTED ARE VALID THROUGH END OF (ML949A)
 SHOPPING COMMENCING ON DATE SHOWN AT TOP OF PAGE

OPEN ACCIDENTS

HAS NO OPEN ACCIDENTS

TROUBLE HISTORY

TT 05-18-2016 STORE UNIT
 UNIT TROUBLE COMMENTS:
 TOW TO SCX FOR STORAGE.

RESOLVED: BY:

TT 05-03-2016 FEDERAL INSPECTOR REPORT ITEMS

UNIT TROUBLE COMMENTS:
 TRASH IN CAB: MAIN GEN PANEL OFF: OIL IN AC ROOM.: L1-R2 BRAKE CYLINDER
 PISTON TRAVEL EXCESSIVE: EXCESSIVE OIL IN ENGINE COMPARTMENT. #2 TM LEAD
 HAS EXCESSIVE OIL.

MECH DEPT RESOLUTION COMMENTS:
 CLEANED CAB. REPLACED PANEL IN MAIN GENERATOR ROOM. ADJUSTED PISTON
 TRAVEL. FOUND OIL LEAK AND REPAIRED ALSO CLEANED ALL OIL FROM A/C ROOM AND
 SUMP.

RESOLVED: 05-04-2016 07:20 BY: MDRWR

LAB ANALYSIS HISTORY

	PB	CU	FE	AL	SI	CR	B	ZN	V100	%F	HD	PPI	OS
05-03-2016	19	27	34	3	9	3	2	2	14.4	221	22	50	31
04-10-2016	20	27	29	3	8	3	2	1	14.0	222	21	59	36
03-13-2016	24	34	44	4	13	3	3	2	13.9	222	23	59	37
02-23-2016	16	33	34	3	10	2	2	1	13.7	222	27	57	36

NOTICES DUE

MDH MO 6653 Dash-2 Locomotive Cab Replacement

MDH MO 6821 Remove Exterior Toilet Dump Slide Valve

MDH MO 6839 Replace Toilet Top - Yard/Local Units

MDH WR 222 Apply Toilet Chemical Sticker to Toilet

MDH WR 235 Replace Toilet Floor Flange Seal -Yard/Local Units

MDH WR 239 Throttle Switch check for EMD units

UNRESOLVED LAB DATA

HAS NO UNRESOLVED LABS