

UNIT INFORMATION SHEETS FOR NS 5142 AT SHOP SCY ON 03/27/17 PAGE 1

TASKS AND INFO LISTED ARE VALID THROUGH END OF SHOPPING COMMENCING ON DATE SHOWN AT TOP OF PAGE (ML949A)

CRITICAL UNIT DATA			
	LAST DONE	SHOP	NEXT DUE
# OIL/WTR SAMP	12/18/16	SPE	01/01/17
# LUBE	12/18/16	SPE	01/31/17
# 3 MONTH - MAINT EXPEDITED	12/18/16	SPE	03/17/17
- 6 MONTH	12/18/16	SPE	06/19/17
- METER	12/18/16	SPE	12/20/17
- 12 MONTH	12/18/16	SPE	12/20/17
- 24/36/48/60	12/15/14	SPE	12/20/17
# EVENT RECORDER	12/18/16	SPE	03/17/17
- EPA 1 YEAR	06/18/16	SPE	06/19/17
- EPA 2 YEAR	06/18/16	SPE	06/23/18
- EPA 3 YEAR	06/17/14	SPE	06/19/17
# EPA 4 YEAR	03/25/13	LPT	03/19/17
# EPA 6 YEAR	04/08/11	LPT	03/19/17
- EPA 12 YEAR	12/18/16	SPE	01/19/29
- MID-LIFE TUNE UP	06/28/13	JUN	07/14/19
- OVERHAUL	02/10/05	JUN	06/08/17
# TRUCK CHANGE	10/13/03	JUN	02/05/15
- RETRO REFLECTIVE	12/12/15	SPE	01/07/26
# BATTERY SET CHANGE	02/03/05	JUN	05/27/15
- DUMP TOILET HOLDING	03/21/17	SPE	04/02/17

AIR COMP: ? AIR DRYER: ? OIL CHG: 03/17/12

RI: 99 EPA: 0 RAILVIEW: N APU: K90

CAB SGNL: N TM TYPE: 723D77,40H BEARING TYPE: HYATT RMT CTL: N

COMPONENT CHANGE HISTORY		
DATE	DESCRIPTION	POS
03-11-2017	SHOE BRAKE, HIGH-FRIC COMP, AAR-H4, 2"	L05
02-25-2017	SHOE BRAKE, HIGH-FRIC COMP, AAR-H4, 2"	L04
02-15-2017	SHOE BRAKE, HIGH-FRIC COMP, AAR-H4, 2"	R04
01-31-2017	BRUSH, CAB HEATER MOTOR	N/A
12-18-2016	LOCO SAMPLE BOTTLE W/ LID, PLASTIC	N/A
12-18-2016	ELEMENT, FUEL AND MUP FILTER, ECOTRANS	N/A
12-18-2016	GASKET, SWELLEX SOLENOID VALVE	N/A
12-18-2016	VALVE, 74VDC, 2TAB, AIR COMP MAGNET	N/A
12-18-2016	BRUSH, CARBON GRADE AY - EMD 8413190	N/A
12-18-2016	DNO BRUSH, CARBON GRADE N39	N/A
12-18-2016	BATTERY, APU 38LB 8.99"L X 5.55"W	N/A
12-18-2016	HORN, NATHAN/AIRCHIME, MODEL P-12345	ALL
12-18-2016	SHOE, COMPOSITE BRAKE 2IN	ALL
12-18-2016	LOCO SAMPLE BOTTLE W/ LID, PLASTIC	N/A
12-18-2016	CARTRIDGE, BELL RINGER, MOTOR/PLUNGER	N/A
12-18-2016	ELEMENT, AIR FILTER, TO ELECT COMPARTMNT	N/A
12-18-2016	GASKET COVER LUBE OIL FILTER MICHIANA	N/A

UNIT INFORMATION SHEETS FOR NS 5142 AT SHOP SCY ON 03/27/17 PAGE 2

TASKS AND INFO LISTED ARE VALID THROUGH END OF SHOPPING COMMENCING ON DATE SHOWN AT TOP OF PAGE (ML949A)

12-18-2016	FILTER, LUBE OIL	ALL
12-18-2016	GASKET COVER FUEL OIL FILTER	N/A
12-18-2016	FILTER, LUBE OIL	N/A
12-18-2016	ELEMENT, FIBERGLASS BAGGY TYPE FILTER	N/A
12-18-2016	SHOE, COMPOSITE BRAKE 2IN	ALL
12-18-2016	ELEMENT, SPIN ON FUEL FILTER	N/A
12-18-2016	ELEMENT, AIR COMPRESSOR FILTER, ROUND	N/A
12-18-2016	ELEMENT, AIR FILTER	N/A
12-18-2016	ELEMENT, 13 & 20 LINE FILTER AND	N/A
12-18-2016	GASKET, RING 3 IN OD CUT-OUT COCKS	N/A
12-18-2016	GASKET, FILTER/BRAKE PIPE STRAINER	N/A
12-18-2016	GASKET, FUEL SIGHT GLASS BOWL TO FILTER	N/A
12-18-2016	SEAL, OIL STRAINER FITS, SEE EXT DESC.	N/A
12-09-2016	WD-40, AEROSOL SPRAY.	N/A
12-07-2016	PORTION, AUTOMATIC BRAKE VALVE 26L, 26C	ALL
12-07-2016	VALVE, A1 CHARGING	ALL
12-07-2016	VALVE, P2A BRAKE APPLICATION	ALL

UNSCHEDULED SHOPPING HISTORY

01-30-2017 SPE
12-09-2016 SPE

LATEST WHEEL DATA

AXLE	LRT	LFH	LFT	RRT	RFH	RFT
1	1 11/16	1 3/16	1 6/16	1 9/16	1 5/16	1 4/16
2	1 10/16	1 4/16	1 5/16	1 10/16	1 4/16	1 6/16
3	1 6/16	1 3/16	1 5/16	1 5/16	1 4/16	1 6/16
4	2 8/16	1 3/16	1 6/16	2 8/16	1 5/16	1 6/16

KIPS READING > 75

POS PEAK DATE
HAS NO WHEEL DATA AVAILABLE

OPEN ACCIDENTS

HAS NO OPEN ACCIDENTS

TROUBLE HISTORY

TT 03-22-2017 STORE UNIT
UNIT TROUBLE COMMENTS:
CONTACT SOC ON ARRIVAL AT SHOP TO HAVE UNIT PLACED IN STORED STATUS.
RESOLVED: BY:

TT 03-11-2017 BRAKE RIGGING TROUBLE
UNIT TROUBLE COMMENTS:
BRAKES NEEDED ADJUSTED

UNIT INFORMATION SHEETS FOR NS 5142 AT SHOP SCY ON 03/27/17 PAGE 3

TASKS AND INFO LISTED ARE VALID THROUGH END OF (ML949A)
SHOPPING COMMENCING ON DATE SHOWN AT TOP OF PAGE

MECH DEPT RESOLUTION COMMENTS:
ADJUSTED BRAKES

COMPONENT(S) USED:
SHOE BRAKE, HIGH-FRIC COMP, AAR-H4, 2"
RESOLVED: 03-11-2017 22:32 BY: MAWE6

TT 02-25-2017 BRAKE RIGGING TROUBLE
UNIT TROUBLE COMMENTS:

BRAKES NEEDED ADJUSTED
MECH DEPT RESOLUTION COMMENTS:

ADJUSTED BRAKES
COMPONENT(S) USED:
SHOE BRAKE, HIGH-FRIC COMP, AAR-H4, 2"
RESOLVED: 02-25-2017 22:44 BY: MAWE6

TT 02-15-2017 BRAKE RIGGING TROUBLE
UNIT TROUBLE COMMENTS:

BRAKES NEEDED ADJUSTED
MECH DEPT RESOLUTION COMMENTS:

ADJUSTED BRAKES
COMPONENT(S) USED:
SHOE BRAKE, HIGH-FRIC COMP, AAR-H4, 2"
RESOLVED: 02-15-2017 19:31 BY: MAWE6

ME 01-30-2017 ENGINE TROUBLE
UNIT TROUBLE COMMENTS:

LCDI CAT: ENGINE ROOM, DEF: ENGINE OIL AND FUEL,OIL LEAK,ALL OF THE ENGINE
OIL HAS LEAKED OUT

MECH DEPT RESOLUTION COMMENTS:
CLEANED AIR BOX DRAINS AND SPARK ARRESTORS, DRAIN SUMP, LOAD BOXED NO OIL
OR FUEL LEAKS FOUND.

RESOLVED: 02-01-2017 03:04 BY: MBJ2H

ME 01-20-2017 CREW CAB TROUBLE
UNIT TROUBLE COMMENTS:

LCDI CAT: CREW CAB PROBLEM , DEF: HEATER TROUBLE,ENG FRONT WALL,

MECH DEPT RESOLUTION COMMENTS:
CHANGED OUT HEATER BRUSHES. FOUND BRUSHES VERY LOW...ALL HEATERS CHECKED

OK
COMPONENT(S) USED:
BRUSH, CAB HEATER MOTOR
RESOLVED: 02-01-2017 01:03 BY: MBJ2H

TT 12-14-2016 HORN / BELL TROUBLE
UNIT TROUBLE COMMENTS:

LCDI CAT: HORN OR BELL, DEF: HORN,SOUNDS WEAK,

MECH DEPT ASSESSMENT COMMENTS:
SHORT HOOD HORNS WEAK

MECH DEPT RESOLUTION COMMENTS:
REPLACED HORNS

UNIT INFORMATION SHEETS FOR NS 5142 AT SHOP SCY ON 03/27/17 PAGE 4

TASKS AND INFO LISTED ARE VALID THROUGH END OF (ML949A)
SHOPPING COMMENCING ON DATE SHOWN AT TOP OF PAGE

COMPONENT(S) USED:
HORN, NATHAN/AIRCHIME, MODEL P-12345
RESOLVED: 12-18-2016 09:51 BY: MBN0C

TT 12-07-2016 AIR BRAKE (COMPONENT)
UNIT TROUBLE COMMENTS:
LCDI CAT: AIR SYSTEM/BRAKES, DEF: AUTOMATIC BRAKE VALVE,OTHER,(JH)UNITS
SELF LAPPING FEATURE ISN'T OPERATING CORRECTLY. TAGGED UNIT AND CONT....TA
MECH DEPT ASSESSMENT COMMENTS:
FOUND GASKET ON P2A BLOWN OUT ON END CAUSING AUTO BRAKE NOT TO LAP.
MECH DEPT RESOLUTION COMMENTS:
RENEWED P2A, A1 CHARGING, AND AUTO BRAKE VALVE, PERFORMED MULTIPLE BRAKE
TESTS WITH NO EXCEPTIONS TAKEN. UNIT LAPPING AS INTENDEED. UNIT OK FOR
SERVICE.

COMPONENT(S) USED:
VALVE, P2A BRAKE APPLICATION
PORTION, AUTOMATIC BRAKE VALVE 26L, 26C
VALVE, A1 CHARGING
RESOLVED: 12-07-2016 21:39 BY: ETAGG

ME 12-07-2016 HORN / BELL TROUBLE
UNIT TROUBLE COMMENTS:
NON-COMPLYING - LCDI CAT: HORN OR BELL, DEF: BELL,RINGS INTERMITTENT,
VALVE STICKS/HARD TO PU,
MECH DEPT RESOLUTION COMMENTS:
LUBRICATED BELL SWITCH
COMPONENT(S) USED:
WD-40. AEROSOL SPRAY.
RESOLVED: 12-09-2016 18:13 BY: B7T7B
WD-40. AEROSOL SPRAY.

LAB ANALYSIS HISTORY

	PB	CU	FE	AL	SI	CR	B	ZN	V100	%F	HD	PPI	OS
12-18-2016	2	8	14	2	6	2	2	2	15.5	220	14	54	26

NOTICES DUE

- MDH MO 6653 Dash-2 Locomotive Cab Replacement
- MDH MO 6839 Replace Toilet Top - Yard/Local Units
- MDH MO 6865 K9 and K9.9 APU 240 VAC Distribution Upgrade
- MDH WR 235 Replace Toilet Floor Flange Seal -Yard/Local Units

UNRESOLVED LAB DATA

HAS NO UNRESOLVED LABS