

UNIT INFORMATION SHEETS FOR NS 5152 AT SHOP SCY ON 04/27/17 PAGE 1

TASKS AND INFO LISTED ARE VALID THROUGH END OF SHOPPING COMMENCING ON DATE SHOWN AT TOP OF PAGE (ML949A)

CRITICAL UNIT DATA			
	LAST DONE	SHOP	NEXT DUE
# OIL/WTR SAMP	12/30/16	CHI	01/13/17
# LUBE	12/30/16	CHI	02/12/17
# 3 MONTH - MAINT EXPEDITED	12/30/16	CHI	03/30/17
- 6 MONTH	12/30/16	CHI	07/01/17
- METER	12/30/16	CHI	12/21/17
- 12 MONTH	12/30/16	CHI	12/21/17
- 24/36/48/60	12/14/14	ELK	12/21/17
# EVENT RECORDER	12/30/16	CHI	03/30/17
- EPA 1 YEAR	06/27/16	CHI	06/29/17
- EPA 2 YEAR	06/27/16	CHI	07/02/18
- EPA 3 YEAR	06/21/15	ELK	06/28/18
- EPA 4 YEAR	06/08/13	ELK	06/18/17
- EPA 6 YEAR	05/28/11	ELK	06/12/17
- EPA 12 YEAR	04/23/05	MDH	05/25/17
# MID-LIFE TUNE UP	01/31/11	JUN	03/10/17
# OVERHAUL	04/23/05	JUN	03/10/17
# TRUCK CHANGE	04/11/05	JUN	07/04/16
- RETRO REFLECTIVE	06/27/16	CHI	07/24/26
- BATTERY SET CHANGE	09/08/16	BEL	10/05/26

AIR COMP: ? AIR DRYER: ? OIL CHG: 10/26/96

RI: EPA: 0 RAILVIEW: N APU: K90

CAB SGNL: N TM TYPE: 723D77,40H BEARING TYPE: HYATT RMT CTL: N

COMPONENT CHANGE HISTORY		
DATE	DESCRIPTION	POS
03-15-2017	RESISTOR, 8 OHM, 400 WATT HEADLIGHT	SH
12-30-2016	CARTRIDGE, BELL RINGER, MOTOR/PLUNGER	N/A
12-30-2016	GASKET, SWELLEX SOLENOID VALVE	N/A
12-30-2016	VALVE, 74VDC, 2TAB, AIR COMP MAGNET	N/A
12-29-2016	ELEMENT, AIR COMPRESSOR FILTER, ROUND	N/A
12-29-2016	ELEMENT, AIR FILTER	N/A
12-29-2016	ELEMENT, 13 & 20 LINE FILTER AND	N/A
12-29-2016	GASKET, RING 3 IN OD CUT-OUT COCKS	N/A
12-29-2016	BRUSH, GRADE AG137	ALL
12-29-2016	GASKET, FILTER/BRAKE PIPE STRAINER	N/A
12-29-2016	BRUSH, GRADE AG137	ALL
12-29-2016	GASKET COVER LUBE OIL FILTER MICHIANA	N/A
12-29-2016	FILTER, LUBE OIL	ALL
12-29-2016	ELEMENT, FIBERGLASS BAGGY TYPE FILTER	N/A
12-29-2016	EXTINGUISHER, FIRE, 20 LBS, DRY CHEMICAL	ALL
12-29-2016	GASKET COVER FUEL OIL FILTER	N/A
12-29-2016	FILTER, LUBE OIL	N/A
12-29-2016	ELEMENT, SPIN ON FUEL FILTER	N/A

UNIT INFORMATION SHEETS FOR NS 5152 AT SHOP SCY ON 04/27/17 PAGE 2

TASKS AND INFO LISTED ARE VALID THROUGH END OF SHOPPING COMMENCING ON DATE SHOWN AT TOP OF PAGE (ML949A)

12-29-2016	FILTER, APU & AIR COMP LUBE OIL	N/A
12-29-2016	SEAL, OIL STRAINER FITS, SEE EXT DESC.	N/A
12-29-2016	SHOE, COMPOSITE BRAKE 2IN	ALL
12-29-2016	SHOE, COMPOSITE BRAKE 2IN	ALL
12-29-2016	GREASE, MULTI PURPOSE 10 oz	ALL
12-29-2016	REFILL, LOCOMOTIVE FIRST AID KIT	ALL
12-29-2016	LOCO SAMPLE BOTTLE W/ LID, PLASTIC	N/A
12-29-2016	LOCO SAMPLE BOTTLE W/ LID, PLASTIC	N/A

UNSCCHEDULED SHOPPING HISTORY

03-14-2017 CHI  
 03-09-2017 CHI 03/01 - REPORTED ELECTRICAL WIRING TROUBLE  
 01-10-2017 CHI 2nd shift repaired horn and worked TROUBLE

LATEST WHEEL DATA

AXLE	LRT	LFH	LFT	RRT	RFH	RFT
1	2 6/16	1 5/16	1 7/16	2 6/16	1 5/16	1 7/16
2	2 1/16	1 2/16	1 5/16	2 2/16	1 2/16	1 5/16
3	2 1/16	1 3/16	1 5/16	2 2/16	1 3/16	1 5/16
4	1 13/16	1 4/16	1 7/16	1 14/16	1 4/16	1 5/16

KIPS READING > 75

POS PEAK DATE  
 HAS NO WHEEL DATA AVAILABLE

OPEN ACCIDENTS

HAS NO OPEN ACCIDENTS

TROUBLE HISTORY

ME 03-22-2017 HORN / BELL TROUBLE  
 UNIT TROUBLE COMMENTS:  
 LCDI CAT: HORN OR BELL, DEF: BELL,RINGS CONTINUOSLY,  
 RESOLVED: BY:

ME 03-22-2017 CREW CAB TROUBLE  
 UNIT TROUBLE COMMENTS:  
 LCDI CAT: CREW CAB PROBLEM , DEF: SEAT DEFECT,CONDUCTOR,WORN OUT. LIKE  
 SITTING ON PLYWOOD  
 RESOLVED: BY:

TT 03-20-2017 STORE UNIT  
 UNIT TROUBLE COMMENTS:  
 CONTACT SOC ON ARRIVAL AT SHOP TO HAVE UNIT PLACED IN STORED STATUS.  
 RESOLVED: BY:

ME 03-14-2017 LIGHTING TROUBLE

UNIT INFORMATION SHEETS FOR NS 5152 AT SHOP SCY ON 04/27/17 PAGE 3

TASKS AND INFO LISTED ARE VALID THROUGH END OF (ML949A)  
SHOPPING COMMENCING ON DATE SHOWN AT TOP OF PAGE

UNIT TROUBLE COMMENTS:

LCDI CAT: LIGHTING PROBLEMS, DEF: HEADLIGHT,OUT SHORT HOOD END,OUT ON SHORT NOSE ROUND HOUSE WORKED ON IT FOR A HOUR COULD NOT GET THEM TO WORK AT RIVERDALE

MECH DEPT ASSESSMENT COMMENTS:

BO RESISTOR

MECH DEPT RESOLUTION COMMENTS:

REPLACED SH END HEAD LIGHT RESISTOR

COMPONENT(S) USED:

RESISTOR, 8 OHM, 400 WATT HEADLIGHT

RESOLVED: 03-15-2017 21:18 BY: MJT88

TT 03-01-2017 ELECTRICAL WIRING TROUBLE

UNIT TROUBLE COMMENTS:

FRONT STEP LIGHTS OUT

MECH DEPT ASSESSMENT COMMENTS:

BROKEN WIRES

MECH DEPT RESOLUTION COMMENTS:

REPLACED WIRES

RESOLVED: 03-09-2017 19:33 BY: MJT88

RESISTOR, 8 OHM, 400 WATT HEADLIGHT

LAB ANALYSIS HISTORY

	PB	CU	FE	AL	SI	CR	B	ZN	V100	%F	HD	PPI	OS
12-29-2016	3	7	9	1	3	1		5	15.4	223	15	45	31

NOTICES DUE

MDH MO 6653 Dash-2 Locomotive Cab Replacement

MDH MO 6865 K9 and K9.9 APU 240 VAC Distribution Upgrade

MDH WR 5911 APPLY CAB SEAT WALL PLATE SUPPORT(IF REQ'D)12A192

UNRESOLVED LAB DATA

12-29-2016: INSPECT FOR AND CORRECT FUEL LEAKS - THE APU OIL VISCOSITY IS LOW IN SYSTEM: AUXILIARY POWER UNIT

12-29-2016: ADD 0.75 GAL OR 1 POUCHES OR 6 BAGS OF BORON TREATMENT.ITY IS LOW IN SYSTEM: COOLING