

UNIT INFORMATION SHEETS FOR NS 5156 AT SHOP SCY ON 03/31/17 PAGE 1

TASKS AND INFO LISTED ARE VALID THROUGH END OF SHOPPING COMMENCING ON DATE SHOWN AT TOP OF PAGE (ML949A)

CRITICAL UNIT DATA			
	LAST DONE	SHOP	NEXT DUE
# OIL/WTR SAMP	01/26/17	SPE	02/09/17
# LUBE	01/26/17	SPE	03/11/17
- 3 MONTH - MAINT EXPEDITED	01/26/17	SPE	04/27/17
- 6 MONTH	01/26/17	SPE	07/28/17
- METER	01/26/17	SPE	01/28/18
- 12 MONTH	01/26/17	SPE	01/28/18
- 24/36/48/60	01/29/15	KNX	01/28/18
- EVENT RECORDER	01/26/17	SPE	04/27/17
- EPA 1 YEAR	01/26/17	SPE	01/28/18
- EPA 2 YEAR	01/26/17	SPE	01/31/19
- EPA 3 YEAR	01/26/17	SPE	02/03/20
- EPA 4 YEAR	11/08/14	ENO	11/18/18
- EPA 6 YEAR	11/08/14	ENO	11/23/20
- EPA 12 YEAR	11/08/14	ENO	12/10/26
- MID-LIFE TUNE UP	05/05/14	JUN	05/20/20
# OVERHAUL	05/12/02	JUN	06/13/14
# TRUCK CHANGE	05/15/02	JUN	06/13/13
- RETRO REFLECTIVE	01/21/16	SPE	02/16/26
- BATTERY SET CHANGE	12/06/13	SCX	01/02/24
# DUMP TOILET HOLDING	03/08/17	SPE	03/20/17

AIR COMP: ? AIR DRYER: ? OIL CHG: 02/03/15

RI: 100 EPA: 0 RAILVIEW: N APU: K90

CAB SGNL: N TM TYPE: 723D77,40H BEARING TYPE: HYATT RMT CTL: N

COMPONENT CHANGE HISTORY		
DATE	DESCRIPTION	POS
02-10-2017	INDICATOR, SPEED, BASE MOUNT	N/A
01-26-2017	LOCO SAMPLE BOTTLE W/ LID, PLASTIC	N/A
01-26-2017	ELEMENT, FUEL AND MUP FILTER, ECOTRANS	N/A
01-26-2017	INJECTOR, FUEL, G4SE, NON-TURBO, TIER 0	ALL
01-26-2017	FILTER, APU & AIR COMP LUBE OIL	N/A
01-26-2017	ELEMENT, SPIN ON FUEL FILTER	N/A
01-26-2017	ELEMENT, AIR FILTER	N/A
01-26-2017	CARTRIDGE, BELL RINGER, MOTOR/PLUNGER	N/A
01-26-2017	SEAL, OIL STRAINER FITS, SEE EXT DESC.	N/A
01-26-2017	GASKET, FUEL SIGHT GLASS BOWL TO FILTER	N/A
01-26-2017	ELEMENT, AIR FILTER, TO ELECT COMPARTMNT	N/A
01-26-2017	GASKET COVER LUBE OIL FILTER MICHIANA	N/A
01-26-2017	FILTER, LUBE OIL	ALL
01-26-2017	ELEMENT, FIBERGLASS BAGGY TYPE FILTER	N/A
01-26-2017	GASKET COVER FUEL OIL FILTER	N/A
01-26-2017	FILTER, LUBE OIL	N/A
01-26-2017	SHOE, COMPOSITE BRAKE 2IN	ALL

UNIT INFORMATION SHEETS FOR NS 5156 AT SHOP SCY ON 03/31/17 PAGE 2

TASKS AND INFO LISTED ARE VALID THROUGH END OF SHOPPING COMMENCING ON DATE SHOWN AT TOP OF PAGE (ML949A)

01-26-2017	VALVE, GURU 35F DL 2.1 COMPLETE W HEX	N/A
01-26-2017	SHOE, COMPOSITE BRAKE 2IN	ALL
01-26-2017	BLADE, 20 IN WIPER	N/A
01-26-2017	LOCO SAMPLE BOTTLE W/ LID, PLASTIC	N/A
01-26-2017	ELEMENT, AIR COMPRESSOR FILTER, ROUND	N/A
12-14-2016	LATCH, DOOR LOCK, CAST STEEL	F
11-23-2016	TM, COMBO, D77/D77B 40 IN HYATT JRN BRG	002
10-27-2016	GROMMET, TRACTION MOTOR	CE
10-27-2016	GASKET COVER FUEL OIL FILTER	N/A
10-27-2016	FILTER, LUBE OIL	N/A
10-27-2016	ELEMENT, SPIN ON FUEL FILTER	N/A
10-27-2016	LOCO SAMPLE BOTTLE W/ LID, PLASTIC	N/A
10-27-2016	LAMP, 50W 75V A19 MED BASE INSIDE FROST	ALL
10-27-2016	BATTERY, APU 38LB 8.99"L X 5.55"W	CE
10-27-2016	SHOE, COMPOSITE BRAKE 2IN	ALL
10-27-2016	SHOE, COMPOSITE BRAKE 2IN	ALL
10-27-2016	FUSE, 400A 250V, EMD LOCO STARTING FUSE	F
10-27-2016	FORM, ME-65 LOCOMOTIVE DAILY INSPECTION	CE
10-27-2016	LAMP BAYONET BASE 30W 75V S11 LOCO	ALL
10-27-2016	LAMP, 5A 37.5V 1828 T3 1/4 MINIATURE BAY	ALL
10-27-2016	LOCO SAMPLE BOTTLE W/ LID, PLASTIC	N/A
10-20-2016	SHOE, COMPOSITE BRAKE 2IN	R02
10-20-2016	SHOE, COMPOSITE BRAKE 2IN	R02
09-30-2016	HORN, NATHAN/AIRCHIME, MODEL P-124	SH

UNSCCHEDULED SHOPPING HISTORY

02-09-2017 SPE
 02-03-2017 SPE
 11-18-2016 SPE
 09-28-2016 SPE

LATEST WHEEL DATA

AXLE	LRT	LFH	LFT	RRT	RFH	RFT
1	1 4/16	1 3/16	1 4/16	1 4/16	1 4/16	1 4/16
2	2 14/16	1 4/16	1 5/16	2 14/16	1 3/16	1 7/16
3	2 15/16	1 2/16	1 7/16	2 15/16	1 2/16	1 7/16
4	2 10/16	1 2/16	1 7/16	2 10/16	1 2/16	1 7/16

KIPS READING > 75

POS PEAK DATE
 HAS NO WHEEL DATA AVAILABLE

OPEN ACCIDENTS

HAS NO OPEN ACCIDENTS

TROUBLE HISTORY

TT 03-20-2017 STORE UNIT

UNIT INFORMATION SHEETS FOR NS 5156 AT SHOP SCY ON 03/31/17 PAGE 3

TASKS AND INFO LISTED ARE VALID THROUGH END OF (ML949A)
SHOPPING COMMENCING ON DATE SHOWN AT TOP OF PAGE

UNIT TROUBLE COMMENTS:

CONTACT SOC ON ARRIVAL AT SHOP TO HAVE UNIT PLACED IN STORED STATUS.
RESOLVED: BY:

ME 02-08-2017 SPEED INDICATOR TROUBLE (LDI 1

UNIT TROUBLE COMMENTS:

LCDI CAT: SPEEDOMETER, DEF: INOPERATIVE,CONTROL STAND,Unit speedometer is inoperative past 7mph. tagged and running as a b-unit until repaired...ta.
..jh

MECH DEPT RESOLUTION COMMENTS:

REPLACED SPEED-O HEAD, TRACK TESTED OK @ ALL SPEEDS

COMPONENT(S) USED:

INDICATOR, SPEED, BASE MOUNT

RESOLVED: 02-10-2017 01:12 BY: MBJ2H

ME 02-03-2017 OIL OUT STACK

UNIT TROUBLE COMMENTS:

LCDI CAT: EXHAUST SYSTEM, DEF: OIL OUT THE STACK,OTHER,TA(CDA)RPTD OIL OUT OF STACK-SHUTDOWN-TAGGED...

MECH DEPT RESOLUTION COMMENTS:

CLEANED OUT AIR BOX DRAINS AND SPARK ARRESTORS. BLOWERS CHECKED OK. LOAD TESTED, READY FOR SERVICE

RESOLVED: 02-07-2017 06:20 BY: MYX34

TT 11-28-2016 CREW CAB TROUBLE

UNIT TROUBLE COMMENTS:

LCDI CAT: CREW CAB PROBLEM , DEF: DOOR,PADLOCK EXTERIOR,TA(AJ) FRONT DOOR LOCK BROKEN, CREW UNABLE TO PUT KEY INTO LOCK TO LOCK FRONT DOOR

MECH DEPT ASSESSMENT COMMENTS:

DOOR LOCK BROKEN

MECH DEPT RESOLUTION COMMENTS:

REPLACED LOCK

COMPONENT(S) USED:

LATCH, DOOR LOCK, CAST STEEL

RESOLVED: 12-14-2016 17:55 BY: MAYG4

TT 11-07-2016 TRACTION MOTOR/BEARING/LOCKED/

UNIT TROUBLE COMMENTS:

LCDI CAT: TRACTION MOTOR, DEF: T/M FIRE,TA(AJ) FIRE/FLAMES FROM TM#2, CUTOFF TM#2, ROLL BY OK.

MECH DEPT ASSESSMENT COMMENTS:

FOUND #2 T/M B/O FLASHED OVER, WILL NEED TO BE REPLACED.

MECH DEPT RESOLUTION COMMENTS:

REPLACED #2TM

COMPONENT(S) USED:

TM, COMBO, D77/D77B 40 IN HYATT JRN BRG

RESOLVED: 11-23-2016 12:28 BY: MKRAO

TM, COMBO, D77/D77B 40 IN HYATT JRN BRG

LAB ANALYSIS HISTORY

	PB	CU	FE	AL	SI	CR	B	ZN	V100	%F	HD	PPI	OS
01-26-2017	5	8	13	2	3	3	1	1		212	211	48	26

UNIT INFORMATION SHEETS FOR NS 5156 AT SHOP SCY ON 03/31/17 PAGE 4

TASKS AND INFO LISTED ARE VALID THROUGH END OF (ML949A)
SHOPPING COMMENCING ON DATE SHOWN AT TOP OF PAGE

10-26-2016	3	6	7	1	4	1	1	15.0	197	16	31	22
10-20-2016	3	6	6	1	3		2	15.4	198	18	30	22
10-02-2016	4	14	9	2	3	1	4	15.3	209	19	40	24

NOTICES DUE

- MDH MO 6650 APU (Engine Shutdown Timer) Reset Circuit Mod.
- MDH MO 6653 Dash-2 Locomotive Cab Replacement
- MDH MO 6865 K9 and K9.9 APU 240 VAC Distribution Upgrade
- MDH WR 8959 APU MODIFICATIONS - SEND UNIT TO JLS FOR MODS.

UNRESOLVED LAB DATA

01-26-2017: RESAMPLE CC OIL ASAP. DO NOT HOLD LOCOMOTIVE.
SYSTEM: OIL