

UNIT INFORMATION SHEETS FOR NS 5158 AT SHOP SCY ON 08/01/16 PAGE 1

TASKS AND INFO LISTED ARE VALID THROUGH END OF SHOPPING COMMENCING ON DATE SHOWN AT TOP OF PAGE (ML949A)

CRITICAL UNIT DATA			
	LAST DONE	SHOP	NEXT DUE
# LUBE	11/18/15	POR	01/01/16
- 3 MONTH - MAINT EXPEDITED	11/18/15	POR	09/11/16
- 6 MONTH	08/17/15	SCX	09/11/16
- METER	02/13/15	BLU	09/11/16
- 12 MONTH	02/13/15	BLU	09/11/16
- 24/36/48/60	02/01/13	SCX	09/11/16
- EVENT RECORDER	11/18/15	POR	09/11/16
# EPA 1 YEAR	02/13/15	BLU	02/15/16
- EPA 2 YEAR	02/13/15	BLU	01/05/17
# EPA 3 YEAR	02/01/13	SCX	02/09/16
- EPA 4 YEAR	05/08/14	POR	05/18/18
- EPA 6 YEAR	02/13/15	BLU	02/28/21
- EPA 12 YEAR	02/13/15	BLU	03/17/27
# MID-LIFE TUNE UP	06/26/07	JUN	10/04/14
# OVERHAUL	05/28/02	JUN	09/12/15
# TRUCK CHANGE	05/21/02	JUN	09/12/14
- RETRO REFLECTIVE	08/10/14	CHA	09/05/24
- BATTERY SET CHANGE	06/16/14	POR	02/12/25

AIR COMP: ? AIR DRYER: ? OIL CHG: 05/18/15  
 RI: EPA: 0 RAILVIEW: N APU: K90  
 CAB SGNL: N TM TYPE: 723D77,40H BEARING TYPE: HYATT RMT CTL: N

COMPONENT CHANGE HISTORY  
 DATE DESCRIPTION POS  
 HAS NO COMPONENT CHANGEOUT HISTORY

UNSCHEDULED SHOPPING HISTORY  
 HAS NO UNSCHEDULED SHOPPING HISTORY

LATEST WHEEL DATA

AXLE	LRT	LFH	LFT	RRT	RFH	RFT
1	1 6/16	1 5/16	1 1/16	0 0/16	1 3/16	1 3/16
2	1 11/16	1 1/16	1 2/16	0 0/16	1 1/16	1 2/16
3	1 15/16	1 5/16	1 1/16	1 15/16	1 3/16	1 3/16
4	0 0/16	0 0/16	1 1/16	1 9/16	1 4/16	1 2/16

KIPS READING > 75  
 POS PEAK DATE  
 HAS NO WHEEL DATA AVAILABLE

OPEN ACCIDENTS  
 HAS NO OPEN ACCIDENTS

UNIT INFORMATION SHEETS FOR NS 5158 AT SHOP SCY ON 08/01/16 PAGE 2

TASKS AND INFO LISTED ARE VALID THROUGH END OF (ML949A)  
SHOPPING COMMENCING ON DATE SHOWN AT TOP OF PAGE

\_\_\_\_\_  
TROUBLE HISTORY  
\_\_\_\_\_

TT 07-02-2016 WHEEL CHAMFER INSPECTION

UNIT TROUBLE COMMENTS:

MEASURE OUTSIDE WHEEL FACE CHAMFER ON #3 & #4 WHEELS. THE MAXIMUM LENGTH OF THIS CHAMFER (MEASURED PARALLEL TO THE SURFACE OF THE CHAMFER) CAN BE NO LONGER THAN 7/16". IF THE CHAMF

RESOLVED: BY:

TT 05-23-2016 STORE UNIT

UNIT TROUBLE COMMENTS:

MOVE TO ROANOKE FOR STORAGE.

MECH DEPT RESOLUTION COMMENTS:

CLOSED

RESOLVED: 05-30-2016 16:41 BY: M7NXW

\_\_\_\_\_  
LAB ANALYSIS HISTORY  
\_\_\_\_\_

PB CU FE AL SI CR B ZN V100 %F HD PPI OS  
HAS NO LAB DATA AVAILABLE

\_\_\_\_\_  
NOTICES DUE  
\_\_\_\_\_

MDH MO 6646 Replace EVAC Toilets

MDH MO 6653 Dash-2 Locomotive Cab Replacement

MDH WR 5911 APPLY CAB SEAT WALL PLATE SUPPORT(IF REQ'D)12A192

MDH WR 8959 APU MODIFICATIONS - SEND UNIT TO JLS FOR MODS.

MDH WR 239 Throttle Switch check for EMD units

\_\_\_\_\_  
UNRESOLVED LAB DATA  
\_\_\_\_\_

HAS NO UNRESOLVED LABS