

UNIT INFORMATION SHEETS FOR NS 5182 AT SHOP SCY ON 03/31/17 PAGE 1

TASKS AND INFO LISTED ARE VALID THROUGH END OF SHOPPING COMMENCING ON DATE SHOWN AT TOP OF PAGE (ML949A)

CRITICAL UNIT DATA			
	LAST DONE	SHOP	NEXT DUE
# LUBE	02/14/17	SPE	03/30/17
# 3 MONTH - MAINT EXPEDITED	02/14/17	SPE	03/24/17
# 6 MONTH	11/21/16	SPE	03/24/17
# METER	05/17/16	SPE	03/24/17
_ 12 MONTH	05/17/16	SPE	05/16/17
# 24/36/48/60	05/11/14	JUN	03/24/17
# EVENT RECORDER	02/14/17	SPE	03/24/17
# EPA 1 YEAR	05/17/16	SPE	03/24/17
# EPA 3 YEAR	05/12/14	JUN	03/24/17
_ MID-LIFE TUNE UP	05/12/14	JUN	05/27/20
# OVERHAUL	06/02/04	JUN	12/10/16
# TRUCK CHANGE	04/10/03	JUN	10/15/14
_ RETRO REFLECTIVE	04/29/13	JUN	05/26/23
_ BATTERY SET CHANGE	01/08/08	SPE	07/12/18

AIR COMP: ? AIR DRYER: ? OIL CHG: 02/13/16

RI: 93 EPA: 0 RAILVIEW: N APU: ?

CAB SGNL: N TM TYPE: 723D77,40H BEARING TYPE: HYATT RMT CTL: N

COMPONENT CHANGE HISTORY			
DATE	DESCRIPTION		POS
02-14-2017	GASKET COVER FUEL OIL FILTER		N/A
02-14-2017	FILTER, LUBE OIL		N/A
02-14-2017	ELEMENT, SPIN ON FUEL FILTER		N/A
02-14-2017	SHOE, COMPOSITE BRAKE 2IN		ALL
02-14-2017	SHOE, COMPOSITE BRAKE 2IN		ALL
02-14-2017	LOCO SAMPLE BOTTLE W/ LID, PLASTIC		N/A
02-14-2017	TREATMENT, LOCO COOLING WATER. FUNNEL		N/A
02-05-2017	HEAD, BRAKE SHOE, ANGLED 5 DEG CANT		N/A
02-04-2017	SWITCH, MICRO, OPERATION ASSEMBLY		ENG
11-21-2016	VALVE, AUTO DRAIN, 500, AIR RESERVOIR		N/A
11-20-2016	SPRING, HANDBRAKE, HOLDING PAWL, TENSION		N/A
11-20-2016	ELEMENT, FIBERGLASS BAGGY TYPE FILTER		N/A
11-20-2016	ELEMENT, FILTER, HVAC/RETURN		RM
11-20-2016	SHOE, COMPOSITE BRAKE 2IN		ALL
11-20-2016	SHOE, COMPOSITE BRAKE 2IN		ALL
11-20-2016	GASKET COVER FUEL OIL FILTER		N/A
11-20-2016	FILTER, LUBE OIL		N/A
11-20-2016	ELEMENT, SPIN ON FUEL FILTER		N/A
11-20-2016	ELEMENT, AIR COMPRESSOR FILTER, ROUND		N/A
11-20-2016	FILTER, APU & AIR COMP LUBE OIL		N/A
11-20-2016	GASKET COVER LUBE OIL FILTER MICHIANA		N/A
11-20-2016	FILTER, LUBE OIL		ALL
11-20-2016	LOCO SAMPLE BOTTLE W/ LID, PLASTIC		N/A

UNIT INFORMATION SHEETS FOR NS 5182 AT SHOP SCY ON 03/31/17 PAGE 2

TASKS AND INFO LISTED ARE VALID THROUGH END OF SHOPPING COMMENCING ON DATE SHOWN AT TOP OF PAGE (ML949A)

11-20-2016	SCREW, CAP HEX SOCKET HD 1/4-20-UNRC	N/A
11-20-2016	GASKET, FUEL SITE GLASS	N/A
11-20-2016	FORM, ME-65 LOCOMOTIVE DAILY INSPECTION	N/A
10-21-2016	TM, COMBO, D77/D77B 40 IN HYATT JRN BRG	004

UNSCCHEDULED SHOPPING HISTORY

02-04-2017	SPE
10-20-2016	SPE
10-14-2016	SPE

LATEST WHEEL DATA

AXLE	LRT	LFH	LFT	RRT	RFH	RFT
1	2 8/16	1 2/16	1 7/16	2 8/16	1 2/16	1 8/16
2	1 12/16	1 2/16	1 5/16	1 14/16	1 2/16	1 7/16
3	2 13/16	1 3/16	1 7/16	2 11/16	1 5/16	1 3/16
4	2 14/16	1 2/16	1 6/16	2 14/16	1 3/16	1 7/16

KIPS READING > 75

POS PEAK DATE
HAS NO WHEEL DATA AVAILABLE

OPEN ACCIDENTS

HAS NO OPEN ACCIDENTS

TROUBLE HISTORY

ME 03-20-2017 CREW CAB TROUBLE
 UNIT TROUBLE COMMENTS:
 LCDI CAT: CREW CAB PROBLEM , DEF: CEILING INSULATION,OTHER,PAINT ON
 CEILING PEELING AND DROPPING OFF FROM CEILING
 RESOLVED: BY:

ME 03-20-2017 SPEED INDICATOR TROUBLE (LDI 1
 UNIT TROUBLE COMMENTS:
 LCDI CAT: SPEEDOMETER, DEF: ERRATIC,CONTROL STAND,
 RESOLVED: BY:

ME 03-20-2017 HORN / BELL TROUBLE
 UNIT TROUBLE COMMENTS:
 LCDI CAT: HORN OR BELL, DEF: BELL,DOES NOT RING,
 RESOLVED: BY:

TT 03-20-2017 STORE UNIT
 UNIT TROUBLE COMMENTS:
 CONTACT SOC ON ARRIVAL AT SHOP TO HAVE UNIT PLACED IN STORED STATUS.
 MECH DEPT ASSESSMENT COMMENTS:

UNIT INFORMATION SHEETS FOR NS 5182 AT SHOP SCY ON 03/31/17 PAGE 3

TASKS AND INFO LISTED ARE VALID THROUGH END OF (ML949A)
SHOPPING COMMENCING ON DATE SHOWN AT TOP OF PAGE

SOC NOTIFIED UPON ARRIVAL
MECH DEPT RESOLUTION COMMENTS:
UNIT PLACED IN STORAGE
RESOLVED: 03-25-2017 11:55 BY: HTYGG

ME 03-20-2017 TOILET TROUBLE
UNIT TROUBLE COMMENTS:
LCDI CAT: CREW CAB PROBLEM , DEF: TOILET,AIR LEAK,HANDLE ON DOOR IS STUCK
AND DOOR WILL NOT CLOSE .. HANGS OPEN INTO CAB
RESOLVED: BY:

ME 03-19-2017 CREW CAB TROUBLE
UNIT TROUBLE COMMENTS:
LCDI CAT: CREW CAB PROBLEM , DEF: WINDOW, DOOR,OTHER,BATHROOM DOOR LATCH
IS BROKEN. DOOR WILL NOT STAY LATCHED WAS A TRAILING UNIT TODAY AND DIDNT
NOTICE UNTIL SHAPPING ENDS BUT DO
RESOLVED: BY:

ME 03-11-2017 TOILET TROUBLE
UNIT TROUBLE COMMENTS:
LCDI CAT: CREW CAB PROBLEM , DEF: TOILET,ODOR,TOILET HAS A VERY BAD ODOR.
NEEDS ATTENTION.

MECH DEPT ASSESSMENT COMMENTS:
CLEANED AND DUMPED TOILET
MECH DEPT RESOLUTION COMMENTS:
CLEANED AND DUMPED TOILET
RESOLVED: 03-19-2017 08:30 BY: MT9QX

TT 02-27-2017 FEDERAL INSPECTOR REPORT ITEMS
UNIT TROUBLE COMMENTS:
FRA FOUND L2 SHOCK TOP BOLT LOOSE
MECH DEPT ASSESSMENT COMMENTS:
REPAIRED
MECH DEPT RESOLUTION COMMENTS:
REPAIRED
RESOLVED: 02-27-2017 14:43 BY: UMEH

TT 02-13-2017 FEDERAL INSPECTOR REPORT ITEMS
UNIT TROUBLE COMMENTS:
LEFT REAR INNER HANDHOLD NOT SECURLEY FASTENED,OIL ON RIGHT WALKWAY,R2
BRAKESHOE OVERLAP.
MECH DEPT ASSESSMENT COMMENTS:
ALL REPAIRED.
MECH DEPT RESOLUTION COMMENTS:
ALL REPAIRED.
RESOLVED: 02-14-2017 07:36 BY: MKRAO

ME 01-31-2017 ALERTOR / CREW CALL
UNIT TROUBLE COMMENTS:
RPTD ALERTER TROUBLE. WILL NOT RESET. TA.(WJ)

UNIT INFORMATION SHEETS FOR NS 5182 AT SHOP SCY ON 03/31/17 PAGE 4

TASKS AND INFO LISTED ARE VALID THROUGH END OF (ML949A)
SHOPPING COMMENCING ON DATE SHOWN AT TOP OF PAGE

MECH DEPT ASSESSMENT COMMENTS:
WAS ABLE TO RESET ALERTER BUT SEEMS TO BE A INTERMITTENT TROUBLE FOUND
ALERTER NOT WORKING AS INTENDED REPLACED WITH NEW PART
MECH DEPT RESOLUTION COMMENTS:
REPLACED ALERTER RESET SWITCH TESTED MULT. TIMES WITHOUT FAIL
COMPONENT(S) USED:
SWITCH, MICRO, OPERATION ASSEMBLY
RESOLVED: 02-04-2017 14:12 BY: YOUE7

ME 12-30-2016 BRAKE RIGGING TROUBLE
UNIT TROUBLE COMMENTS:
LCDI CAT: BRAKE RIGGING, DEF: BRAKE HEAD/SHOE HEAD, BRAKE SHOE IS
COMPLETELY GONE.
MECH DEPT ASSESSMENT COMMENTS:
RENEWED SHOES AS NEEDED. BRAKE HEADS ARE SEVERELY WORN CAUSING SHOES TO
CRACK AND BREAK...L3 L4 FROM THE F END NEEDS BRAKE HEADS REPLACED
MECH DEPT RESOLUTION COMMENTS:
REPLACED L3 AND L4 BRAKE HEADS.
COMPONENT(S) USED:
HEAD, BRAKE SHOE, ANGLED 5 DEG CANT
RESOLVED: 02-05-2017 04:09 BY: W38KH

ME 12-07-2016 DAILY SERVICING / SUPPLIES L
UNIT TROUBLE COMMENTS:
LCDI CAT: BRAKE RIGGING, DEF: EXCESSIVE PISTON TRAVEL, SEVERAL PISTONS
NEED ADJUSTMENT.
MECH DEPT RESOLUTION COMMENTS:
ADJUSTED AS NEEDED
RESOLVED: 02-01-2017 12:35 BY: MCPFS

ME 11-22-2016 LIGHTING TROUBLE
UNIT TROUBLE COMMENTS:
LCDI CAT: LIGHTING PROBLEMS, DEF: HEADLIGHT,OUT LONG HOOD END,
MECH DEPT ASSESSMENT COMMENTS:
FOUND LUG BURNT OFF RESISTOR
MECH DEPT RESOLUTION COMMENTS:
REPAIRED LUG
RESOLVED: 02-01-2017 12:35 BY: MCPFS

TT 11-15-2016 CREW CAB TROUBLE
UNIT TROUBLE COMMENTS:
LCDI CAT: CREW CAB PROBLEM , DEF: HEATER TROUBLE,TOILET SIDEWALL,
MECH DEPT RESOLUTION COMMENTS:
REPAIRED BURNT LEAD ON TOILET HEATER
RESOLVED: 11-20-2016 20:21 BY: M3JHS

TT 11-15-2016 LIGHTING TROUBLE
UNIT TROUBLE COMMENTS:
LCDI CAT: LIGHTING PROBLEMS, DEF: HEADLIGHT,OTHER,HEADLIGHTS WORK
CONTROLLED FROM TRAILING UNIT ONLY

UNIT INFORMATION SHEETS FOR NS 5182 AT SHOP SCY ON 03/31/17 PAGE 5

TASKS AND INFO LISTED ARE VALID THROUGH END OF (ML949A)
 SHOPPING COMMENCING ON DATE SHOWN AT TOP OF PAGE

MECH DEPT RESOLUTION COMMENTS:
 REPAIRED INCORRECT WIRING ON RHS SWITCH (HF9 & HD9 WERE INTERCHANGED)
 RESOLVED: 11-20-2016 21:30 BY: M3JHS

TT 10-21-2016 WHEEL TRUE/ WHEEL TROUBLE
 UNIT TROUBLE COMMENTS:
 #4 TM-NEEDS REPLACED, B/O WHEEL THIN FLANGE
 MECH DEPT ASSESSMENT COMMENTS:
 REPLACED TRACTION MOTOR
 MECH DEPT RESOLUTION COMMENTS:
 REPLACED TRACTION MOTOR..TRACK TESTED AND MEGGED OK
 COMPONENT(S) USED:
 TM, COMBO, D77/D77B 40 IN HYATT JRN BRG
 RESOLVED: 10-21-2016 10:49 BY: MHYDU

TT 10-13-2016 FEDERAL INSPECTOR REPORT ITEMS
 UNIT TROUBLE COMMENTS:
 RPT #124, ITM #1, ID GK #M5105 = L1 BRAKE GEAR NOT ALIGNED TO WHEEL TREAD.
 IB SPE
 MECH DEPT RESOLUTION COMMENTS:
 ADJUSTED BRAKE RIGGING TO ALIGN TO WHEEL
 RESOLVED: 10-20-2016 11:29 BY: MKRAO

TT 10-05-2016 BRAKE RIGGING TROUBLE
 UNIT TROUBLE COMMENTS:
 LCDI CAT: BRAKE RIGGING, DEF: BRAKE HEAD/SHOE HEAD,OTHER,(SV) BRAKES ON
 TRUCK 2 WONT COMPLETELY RELEASE FROM WHEELS...TA
 MECH DEPT ASSESSMENT COMMENTS:
 CUT OUT TRUCK 2, PISTON WENT ALL THE WAY IN BUT BRAKES STILL WONT RELEASE,
 ADVISED MECHANICAL ASSISTANCE
 MECH DEPT RESOLUTION COMMENTS:
 FOUND BRAKE BINDING & ADJUSTED OUT FOR SLACK.
 RESOLVED: 10-20-2016 13:03 BY: MKRAO
 TM, COMBO, D77/D77B 40 IN HYATT JRN BRG

LAB ANALYSIS HISTORY

	PB	CU	FE	AL	SI	CR	B	ZN	V100	%F	HD	PPI	OS
03-25-2017	4	15	17	2	5	5	2	1	15.4	219	18	84	31
02-13-2017	6	18	22	2	9	5	3	1	15.4	219	16	80	30
11-19-2016	7	23	31	2	8	6	4	2	15.4	218	17	100	32

NOTICES DUE

MDH MO 6653 Dash-2 Locomotive Cab Replacement

UNRESOLVED LAB DATA

UNIT INFORMATION SHEETS FOR NS 5182 AT SHOP SCY ON 03/31/17 PAGE 6

TASKS AND INFO LISTED ARE VALID THROUGH END OF (ML949A)
SHOPPING COMMENCING ON DATE SHOWN AT TOP OF PAGE

03-25-2017: ADD 4 GALS OR 4 POUCHES OR 24 BAGS OF BORON TREATMENT.
SYSTEM: COOLING