

UNIT INFORMATION SHEETS FOR NS 5157 AT SHOP SCX ON 06/25/17 PAGE 1

TASKS AND INFO LISTED ARE VALID THROUGH END OF (ML949A)
 SHOPPING COMMENCING ON DATE SHOWN AT TOP OF PAGE

 CRITICAL UNIT DATA

	LAST DONE	SHOP	NEXT DUE
# OIL/WTR SAMP	03/27/17	SPE	04/10/17
# LUBE	03/27/17	SPE	05/10/17
# 3 MONTH - MAINT EXPEDITED	03/27/17	SPE	06/25/17
# 6 MONTH	12/28/16	SPE	06/25/17
_ METER	09/25/16	SPE	09/26/17
_ 12 MONTH	09/25/16	SPE	09/26/17
_ 24/36/48/60	09/17/15	JUN	09/24/18
# EVENT RECORDER	03/27/17	SPE	06/25/17
_ EPA 1 YEAR	09/25/16	SPE	09/27/17
# EPA 3 YEAR	07/09/14	JUN	06/26/17
_ MID-LIFE TUNE UP	07/09/14	JUN	01/06/21
_ OVERHAUL	09/30/06	JUN	04/16/19
# TRUCK CHANGE	03/26/01	JUN	10/07/12
_ RETRO REFLECTIVE	09/17/15	JUN	10/13/25
# DUMP TOILET HOLDING	04/22/17	SPE	05/04/17

AIR COMP: ? AIR DRYER: ? OIL CHG: 06/07/97

RI: 74 EPA: 0 RAILVIEW: Y APU: ?

CAB SGNL: N TM TYPE: 723D77,40H BEARING TYPE: HYATT RMT CTL: N

Right side AEI tag(s) on unit is(are) defective.
 Replace transponder (AEI) tag(s) during this shopping.

 EMISSION CRITICAL PARTS

ENGINE LABEL:	EMD001-EMDK0645EBL
LOCO LABEL:	EMD001-EMDK0645EBL
EPA COMPLIANCE:	0-TIER 0
EPA REGULATION:	A-92
Turbo/GE LP Turbo	N/A-NOT APPLICABLE
GE HP/EMD HPC Turbo	
Injector/Pump	M-EMD MUI
Injector/Nozzle ID	316-376316 EMD 8478045 8,12,
Master Connecting Rod PA	N/A-NOT APPLICABLE
Art Connecting Rod PA	N/A-N/A
Power Assembly	N/A-NOT APPLICABLE
Short Power Assembly (PA)	583979-JUN MUI 645E TIER 0
Air to Air Intercooler	N/A-NOT APPLICABLE
Air to Water Intercooler	N/A-NOT APPLICABLE
Camshaft (Left End)	N/A-NOT APPLICABLE
Camshaft (Left Mid):	N/A-NOT APPLICABLE
Camshaft (Right End)	N/A-NOT APPLICABLE
Camshaft (Right Mid):	N/A-NOT APPLICABLE
Piston Ring Kit	N/A-NOT APPLICABLE
EGU/ECU/ECM/Governor	321957-EMD 8482396 16-645E

LEFT CAM POS 1:	N/A-NOT APPLICABLE
LEFT CAM POS 2:	N/A-NOT APPLICABLE
LEFT CAM POS 3:	N/A-NOT APPLICABLE
LEFT CAM POS 4:	N/A-NOT APPLICABLE
LEFT CAM POS 5:	N/A-NOT APPLICABLE
LEFT CAM POS 6:	N/A-NOT APPLICABLE
LEFT CAM POS 7:	N/A-NOT APPLICABLE
LEFT CAM POS 8:	N/A-NOT APPLICABLE
LEFT JOURNAL POS 1:	N/A-NOT APPLICABLE
LEFT JOURNAL POS 2:	N/A-NOT APPLICABLE
LEFT JOURNAL POS 3:	N/A-NOT APPLICABLE
LEFT JOURNAL POS 4:	N/A-NOT APPLICABLE
LEFT JOURNAL POS 5:	N/A-NOT APPLICABLE
LEFT JOURNAL POS 6:	N/A-NOT APPLICABLE
LEFT JOURNAL POS 7:	N/A-NOT APPLICABLE
LEFT JOURNAL POS 8:	N/A-NOT APPLICABLE
LEFT JOURNAL POS 9:	N/A-NOT APPLICABLE
RIGHT CAM POS 1:	N/A-NOT APPLICABLE
RIGHT CAM POS 2:	N/A-NOT APPLICABLE
RIGHT CAM POS 3:	N/A-NOT APPLICABLE
RIGHT CAM POS 4:	N/A-NOT APPLICABLE
RIGHT CAM POS 5:	N/A-NOT APPLICABLE
RIGHT CAM POS 6:	N/A-NOT APPLICABLE
RIGHT CAM POS 7:	N/A-NOT APPLICABLE
RIGHT CAM POS 8:	N/A-NOT APPLICABLE
RIGHT JOURNAL POS 1:	N/A-NOT APPLICABLE
RIGHT JOURNAL POS 2:	N/A-NOT APPLICABLE
RIGHT JOURNAL POS 3:	N/A-NOT APPLICABLE
RIGHT JOURNAL POS 4:	N/A-NOT APPLICABLE
RIGHT JOURNAL POS 5:	N/A-NOT APPLICABLE
RIGHT JOURNAL POS 6:	N/A-NOT APPLICABLE
RIGHT JOURNAL POS 7:	N/A-NOT APPLICABLE
RIGHT JOURNAL POS 8:	N/A-NOT APPLICABLE
RIGHT JOURNAL POS 9:	N/A-NOT APPLICABLE

UNIT INFORMATION SHEETS FOR NS 5157 AT SHOP SCX ON 06/25/17 PAGE 2

TASKS AND INFO LISTED ARE VALID THROUGH END OF (ML949A)
SHOPPING COMMENCING ON DATE SHOWN AT TOP OF PAGECOMPONENT CHANGE HISTORY

DATE	DESCRIPTION	POS
04-26-2017	AMMETER, MOTORING/BRAKING, DUAL RANGE	N/A
04-26-2017	MODULE, TH13, THROTTLE RESPONSE	N/A
04-15-2017	MODULE, SE10, EMD	F
03-27-2017	MODULE, AN13, ANNUNCIATOR	N/A
03-27-2017	TM, COMBO, D77/D77B 40 IN HYATT JRN BRG	001
03-27-2017	TOILET, NARROW, V FRONT, SS, BOT DRAIN	ALL
03-27-2017	GASKET, EXHAUST MANIFOLD TO TOP DECK	ALL
03-27-2017	TOILET, NARROW, V FRONT, SS, BOT DRAIN	N/A
03-26-2017	SHOE, COMPOSITE BRAKE 2IN	ALL
03-26-2017	SHOE, COMPOSITE BRAKE 2IN	ALL
03-26-2017	LAMP, LOCO WALKWAY LIGHT, NLIGHT LED	SH
03-26-2017	BRUSH, GRADE AG137	ALL
03-26-2017	BRUSH, GRADE AG137	ALL
03-26-2017	BRUSH, TRACTION MOTOR SD60 EMD 9582217	ALL
03-26-2017	BRUSH, TRACTION MOTOR SD60 EMD 9582217	ALL
03-26-2017	FILTER, HVAC, 20" X 20" X 2"	UF
03-26-2017	GASKET COVER FUEL OIL FILTER	N/A
03-26-2017	FILTER, LUBE OIL	N/A
03-26-2017	ELEMENT, SPIN ON FUEL FILTER	N/A
03-26-2017	LOCO SAMPLE BOTTLE W/ LID, PLASTIC	N/A
12-27-2016	ELEMENT, FIBERGLASS BAGGY TYPE FILTER	N/A
12-27-2016	TM, COMBO, D77/D77B 40 IN HYATT JRN BRG	002
12-27-2016	GASKET COVER LUBE OIL FILTER MICHIANA	N/A
12-27-2016	FILTER, LUBE OIL	ALL
12-27-2016	GASKET COVER FUEL OIL FILTER	N/A
12-27-2016	FILTER, LUBE OIL	N/A
12-27-2016	SHOE, COMPOSITE BRAKE 2IN	ALL
12-27-2016	ELEMENT, SPIN ON FUEL FILTER	N/A
12-27-2016	ELEMENT, AIR COMPRESSOR FILTER, ROUND	N/A
12-27-2016	FILTER, APU & AIR COMP LUBE OIL	N/A
12-27-2016	LOCO SAMPLE BOTTLE W/ LID, PLASTIC	N/A
12-27-2016	BLOWER, GRID, HIGH PROFILE, 18HP	N/A

UNSCHEDULED SHOPPING HISTORY

04-19-2017	SPE	tow 158-G'BORO
04-15-2017	SPE	tow 158-G'BORO
03-25-2017	SPE	tow 158-G'BORO

LATEST WHEEL DATA

AXLE	LRT	LFH	LFT	RRT	RFH	RFT
1	2 12/16	1 1/16	1 4/16	2 12/16	1 2/16	1 2/16
2	3 1/16	1 1/16	1 6/16	3 1/16	1 2/16	1 6/16
3	1 8/16	1 1/16	1 5/16	1 6/16	1 3/16	1 2/16
4	2 4/16	1 1/16	1 4/16	2 3/16	1 2/16	1 3/16

UNIT INFORMATION SHEETS FOR NS 5157 AT SHOP SCX ON 06/25/17 PAGE 3

TASKS AND INFO LISTED ARE VALID THROUGH END OF (ML949A)
SHOPPING COMMENCING ON DATE SHOWN AT TOP OF PAGE

KIPS READING > 75

POS PEAK DATE
HAS NO WHEEL DATA AVAILABLE

OPEN ACCIDENTS

HAS NO OPEN ACCIDENTS

TROUBLE HISTORY

TT 05-20-2017 BRAKE RIGGING TROUBLE
UNIT TROUBLE COMMENTS:
BRAKES NEEDED ADJUSTED
MECH DEPT RESOLUTION COMMENTS:
ADJUSTED BRAKES
RESOLVED: 05-20-2017 22:46 BY: MAWE6

TT 05-07-2017 BRAKE RIGGING TROUBLE
UNIT TROUBLE COMMENTS:
BRAKES NEEDED ADJUSTED
MECH DEPT RESOLUTION COMMENTS:
ADJUSTED BRAKES
RESOLVED: 05-07-2017 22:53 BY: MAWE6

TT 05-02-2017 STORE UNIT
UNIT TROUBLE COMMENTS:
ROUTE TO SCX FOR STORAGE. CONTACT SOC UPON ARRIVAL AT SHOP TO HAVE UNIT
PLACED IN STORED STATUS.
RESOLVED: BY:

ME 04-20-2017 NOT LOADING PROPERLY/WSA/TRANS
UNIT TROUBLE COMMENTS:
LCDI CAT: LOADING TROUBLE , DEF: NO AMPS IN POWER, OTHER,
MECH DEPT ASSESSMENT COMMENTS:
SPE INSPECTED, WORKED NLP SHEETS. FOUND TH13 B/O AND AMP METER STICKING
MECH DEPT RESOLUTION COMMENTS:
REPLACED TH13 AND AMP METER, HAD NO FURTHER ISSUES. TESTED OUT UNIT OK.
LOAD TESTED STALL TESTED HAD NO FURTHER ISSUES.
COMPONENT(S) USED:
MODULE, TH13, THROTTLE RESPONSE
AMMETER, MOTORING/BRAKING, DUAL RANGE
RESOLVED: 04-26-2017 14:41 BY: M73FP

ME 04-19-2017 NOT LOADING PROPERLY/WSA/TRANS
UNIT TROUBLE COMMENTS:
LCDI CAT: LOADING TROUBLE , DEF: NO AMPS IN DB AND POWER, OTHER,
MECH DEPT ASSESSMENT COMMENTS:
SPE ACK, RESOLVED OTHER REPORT

UNIT INFORMATION SHEETS FOR NS 5157 AT SHOP SCX ON 06/25/17 PAGE 4

TASKS AND INFO LISTED ARE VALID THROUGH END OF (ML949A)
SHOPPING COMMENCING ON DATE SHOWN AT TOP OF PAGE

MECH DEPT RESOLUTION COMMENTS:

RESOLVED OTHER REPORT

RESOLVED: 04-26-2017 14:44 BY: M73FP

ME 04-14-2017 NOT LOADING PROPERLY/WSA/TRANS

UNIT TROUBLE COMMENTS:

LCDI CAT: LOADING TROUBLE , DEF: LOADS LITE IN POWER,OTHER,

MECH DEPT ASSESSMENT COMMENTS:

USED TSG, FOUND SE 10 B/O. CHECKS MAIN GEN. FUSES AND BRUSHES, OPEN BACK
MODULES CABINET DOOR CHECK FOR UNUSUAL APPEARANCE. TEST MODULES, SEAT ALL
MODULES.

MECH DEPT RESOLUTION COMMENTS:

REPLACED SE 10. STATIC LOAD, TRACK TEST. LOAD 1500AMPS IN NOTCH 8

COMPONENT(S) USED:

MODULE, SE10, EMD

RESOLVED: 04-15-2017 22:22 BY: HAT1S

ME 04-14-2017 CREW CAB TROUBLE

UNIT TROUBLE COMMENTS:

LCDI CAT: CREW CAB PROBLEM , DEF: CABINET DOORS,OTHER,

MECH DEPT ASSESSMENT COMMENTS:

FOUND DOOR OUT OF SLOT

MECH DEPT RESOLUTION COMMENTS:

PUT THE DOOR BACK AND LATCHED UP.

RESOLVED: 04-15-2017 22:11 BY: HAT1S

ME 04-14-2017 ELECTRICAL WIRING TROUBLE

UNIT TROUBLE COMMENTS:

LCDI CAT: ELECTRICAL MISC. , DEF: ELECT. SWITCH/BREAKER,OTHER,

MECH DEPT RESOLUTION COMMENTS:

RESOLVED WITH NLP

RESOLVED: 04-15-2017 22:13 BY: HAT1S

ME 03-15-2017 NOT LOADING PROPERLY/WSA/TRANS

UNIT TROUBLE COMMENTS:

LCDI CAT: LOADING TROUBLE , DEF: WHEEL SLIP INDICATION,TM#1 BURNS RAIL,

MECH DEPT RESOLUTION COMMENTS:

WILL CLEAR ON OTHER REPORT

RESOLVED: 03-27-2017 13:02 BY: MKRAO

ME 03-15-2017 NOT LOADING PROPERLY/WSA/TRANS

UNIT TROUBLE COMMENTS:

LCDI CAT: LOADING TROUBLE , DEF: LOADS LITE IN POWER,OTHER,

MECH DEPT RESOLUTION COMMENTS:

DUPLICATE REPORT

RESOLVED: 03-27-2017 05:16 BY: MYX34

ME 01-06-2017 NOT LOADING PROPERLY/WSA/TRANS

UNIT TROUBLE COMMENTS:

LCDI CAT: LOADING TROUBLE , DEF: NO AMPS IN POWER,OTHER,UNIT WILL NOT

UNIT INFORMATION SHEETS FOR NS 5157 AT SHOP SCX ON 06/25/17 PAGE 5

TASKS AND INFO LISTED ARE VALID THROUGH END OF (ML949A)
SHOPPING COMMENCING ON DATE SHOWN AT TOP OF PAGE

LOAD AS IT SHOULD. STOPS LOADING . TA(SC)

MECH DEPT ASSESSMENT COMMENTS:

THIRD TIME OFFENDER FOR NLP. CONTACT RELIABILITY TEAM BEFORE RELEASING.
(MARTY SMITH)..RPTD AGAIN, 3/8@8:00AM.TRAIN 235.TA.(WJ)

MECH DEPT RESOLUTION COMMENTS:

MEGGED UNIT AND FOUND #1 TM ARMATURE GROUNDED, REPLACED TM MEGGED AGAIN
AND ALL MEGGED CLEAR SPOKE WITH MARTY SMITH AND OKED FOR SERVICE

COMPONENT(S) USED:

TM, COMBO, D77/D77B 40 IN HYATT JRN BRG

RESOLVED: 03-27-2017 13:57 BY: MKRAO

TM, COMBO, D77/D77B 40 IN HYATT JRN BRG

LAB ANALYSIS HISTORY

	PB	CU	FE	AL	SI	CR	B	ZN	V100	%F	HD	PPI	OS
03-26-2017	20	29	34	4	11	12	1	5	15.2	218	20	64	31
12-27-2016	12	14	19	2	13	4	1	3	15.5	219	19	43	24

NOTICES DUE

MDH MO 6727 Dash 2 Battery Saver ZTR

MDH WR 234 TEST HORN FRA - CHA or JUN ONLY

UNRESOLVED LAB DATA

HAS NO UNRESOLVED LABS