

UNIT INFORMATION SHEETS FOR NS 5184 AT SHOP SCY ON 06/20/17 PAGE 1

TASKS AND INFO LISTED ARE VALID THROUGH END OF (ML949A)
SHOPPING COMMENCING ON DATE SHOWN AT TOP OF PAGE

CRITICAL UNIT DATA

	LAST DONE	SHOP	NEXT DUE
# OIL/WTR SAMP	03/09/17	SCX	03/23/17
# LUBE	03/10/17	SCX	04/23/17
# 3 MONTH - MAINT EXPEDITED	03/10/17	SCX	06/06/17
_ 6 MONTH	03/10/17	SCX	09/05/17
_ METER	09/03/16	JUN	09/05/17
_ 12 MONTH	09/03/16	JUN	09/05/17
_ 24/36/48/60	02/01/15	SCX	03/12/18
# EVENT RECORDER	03/10/17	SCX	06/06/17
_ EPA 1 YEAR	09/03/16	JUN	09/05/17
_ EPA 3 YEAR	09/03/16	JUN	09/11/19
_ MID-LIFE TUNE UP	09/03/16	JUN	09/19/22
_ OVERHAUL	09/03/16	JUN	10/05/28
# TRUCK CHANGE	07/30/98	ATL	03/15/10
_ RETRO REFLECTIVE	09/03/16	JUN	09/30/26
_ BATTERY SET CHANGE	05/29/15	ELK	09/13/25

AIR COMP: ? AIR DRYER: ? OIL CHG: 09/04/06

RI: 90 EPA: A RAILVIEW: N APU: ?

CAB SGNL: N TM TYPE: 723D77,40H BEARING TYPE: HYATT RMT CTL: N

EMISSION CRITICAL PARTS

ENGINE LABEL:	EMD002-EMDK0645RBL
LOCO LABEL:	EMD002-EMDK0645RBL
EPA COMPLIANCE:	A-TIER 0+
EPA REGULATION:	B-1033
Turbo/GE LP Turbo	N/A-NOT APPLICABLE
GE HP/EMD HPC Turbo	
Injector/Pump	M-EMD MUI
Injector/Nozzle ID	453-154453 EMD 40100567 8,12
Master Connecting Rod PA	N/A-NOT APPLICABLE
Art Connecting Rod PA	N/A-N/A
Power Assembly	940318-JUN 645 TIER 0+,1033
Short Power Assembly (PA)	940318-JUN 645 TIER 0+,1033
Air to Air Intercooler	N/A-NOT APPLICABLE
Air to Water Intercooler	N/A-NOT APPLICABLE
Camshaft (Left End)	731867-EMD 8419849
Camshaft (Left Mid):	N/A-NOT APPLICABLE
Camshaft (Right End)	731867-EMD 8419849
Camshaft (Right Mid):	N/A-NOT APPLICABLE
Piston Ring Kit	N/A-NOT APPLICABLE
EGU/ECU/ECM/Governor	321957-EMD 8482396 16-645E
LEFT CAM POS 1:	N/A-NOT APPLICABLE
LEFT CAM POS 2:	N/A-NOT APPLICABLE

LEFT CAM POS 3:	N/A-NOT APPLICABLE
LEFT CAM POS 4:	N/A-NOT APPLICABLE
LEFT CAM POS 5:	N/A-NOT APPLICABLE
LEFT CAM POS 6:	N/A-NOT APPLICABLE
LEFT CAM POS 7:	N/A-NOT APPLICABLE
LEFT CAM POS 8:	N/A-NOT APPLICABLE
LEFT JOURNAL POS 1:	N/A-NOT APPLICABLE
LEFT JOURNAL POS 2:	N/A-NOT APPLICABLE
LEFT JOURNAL POS 3:	N/A-NOT APPLICABLE
LEFT JOURNAL POS 4:	N/A-NOT APPLICABLE
LEFT JOURNAL POS 5:	N/A-NOT APPLICABLE
LEFT JOURNAL POS 6:	N/A-NOT APPLICABLE
LEFT JOURNAL POS 7:	N/A-NOT APPLICABLE
LEFT JOURNAL POS 8:	N/A-NOT APPLICABLE
LEFT JOURNAL POS 9:	N/A-NOT APPLICABLE
RIGHT CAM POS 1:	N/A-NOT APPLICABLE
RIGHT CAM POS 2:	N/A-NOT APPLICABLE
RIGHT CAM POS 3:	N/A-NOT APPLICABLE
RIGHT CAM POS 4:	N/A-NOT APPLICABLE
RIGHT CAM POS 5:	N/A-NOT APPLICABLE
RIGHT CAM POS 6:	N/A-NOT APPLICABLE
RIGHT CAM POS 7:	N/A-NOT APPLICABLE
RIGHT CAM POS 8:	N/A-NOT APPLICABLE
RIGHT JOURNAL POS 1:	N/A-NOT APPLICABLE
RIGHT JOURNAL POS 2:	N/A-NOT APPLICABLE
RIGHT JOURNAL POS 3:	N/A-NOT APPLICABLE
RIGHT JOURNAL POS 4:	N/A-NOT APPLICABLE
RIGHT JOURNAL POS 5:	N/A-NOT APPLICABLE
RIGHT JOURNAL POS 6:	N/A-NOT APPLICABLE
RIGHT JOURNAL POS 7:	N/A-NOT APPLICABLE
RIGHT JOURNAL POS 8:	N/A-NOT APPLICABLE
RIGHT JOURNAL POS 9:	N/A-NOT APPLICABLE

UNIT INFORMATION SHEETS FOR NS 5184 AT SHOP SCY ON 06/20/17 PAGE 2

TASKS AND INFO LISTED ARE VALID THROUGH END OF (ML949A)
 SHOPPING COMMENCING ON DATE SHOWN AT TOP OF PAGE

 COMPONENT CHANGE HISTORY

DATE	DESCRIPTION	POS
03-21-2017	SWITCH, ENGINE RUN CONTROL & FUEL PUMP	ALL
03-10-2017	HEATER, CAB, ELECTRIC, 3KW, R.S. & L.S.	N/A
03-09-2017	BRUSH, GRADE AG137	ALL
03-09-2017	BRUSH, TRACTION MOTOR SD60 EMD 9582217	ALL
03-09-2017	BRUSH, CARBON GRADE DE-8	N/A
03-09-2017	BRUSH, GRADE AG137	ALL
03-09-2017	BRUSH, TRACTION MOTOR SD60 EMD 9582217	ALL
03-09-2017	SPRING, HANDBRAKE, HOLDING PAWL, TENSION	N/A
03-09-2017	ELEMENT, FIBERGLASS BAGGY TYPE FILTER	N/A
03-09-2017	GASKET COVER FUEL OIL FILTER	N/A
03-09-2017	ELEMENT, AIR COMPRESSOR FILTER, ROUND	N/A
03-09-2017	FILTER, APU & AIR COMP LUBE OIL	N/A
03-09-2017	FILTER, LUBE OIL	N/A
03-09-2017	GASKET COVER LUBE OIL FILTER MICHIANA	N/A
03-09-2017	ELEMENT, SPIN ON FUEL FILTER	N/A
03-09-2017	FILTER, LUBE OIL	ALL
03-09-2017	SHOE, COMPOSITE BRAKE 2IN	ALL
03-09-2017	SHOE, COMPOSITE BRAKE 2IN	ALL
03-09-2017	LOCO SAMPLE BOTTLE W/ LID, PLASTIC	N/A
01-31-2017	BRUSH, CAB HEATER, SD40-2 LOCOS	ALL

 UNSCHEDULED SHOPPING HISTORY

HAS NO UNSCHEDULED SHOPPING HISTORY

 LATEST WHEEL DATA

AXLE	LRT	LFH	LFT	RRT	RFH	RFT
1	1 15/16	1 3/16	1 6/16	1 15/16	1 3/16	1 8/16
2	1 8/16	1 3/16	1 7/16	1 8/16	1 3/16	1 8/16
3	1 12/16	1 3/16	1 7/16	1 11/16	1 3/16	1 8/16
4	2 3/16	1 3/16	1 7/16	2 3/16	1 3/16	1 8/16

 KIPS READING > 75

POS PEAK DATE
 HAS NO WHEEL DATA AVAILABLE

 OPEN ACCIDENTS

HAS NO OPEN ACCIDENTS

 TROUBLE HISTORY

TT 06-15-2017 STORE UNIT
 UNIT TROUBLE COMMENTS:

UNIT INFORMATION SHEETS FOR NS 5184 AT SHOP SCY ON 06/20/17 PAGE 3

TASKS AND INFO LISTED ARE VALID THROUGH END OF (ML949A)
SHOPPING COMMENCING ON DATE SHOWN AT TOP OF PAGE

PER MARCUS FOGLE, CONTACT SOC UPON ARRIVAL AT SHOP TO HAVE UNIT PUT BACK INTO STORAGE.

RESOLVED: BY:

TT 06-06-2017 FEDERAL INSPECTOR REPORT ITEMS

UNIT TROUBLE COMMENTS:

R2 AND R4 BRAKE HEAD NOT ALIGNED TO WHEEL AND WATER FILL PIPE CLAMP MISSING

RESOLVED: BY:

ME 04-20-2017 AIR BRAKE (COMPONENT)

UNIT TROUBLE COMMENTS:

LCDI CAT: AIR SYSTEM/BRAKES, DEF: BRAKE PIPE,BROKEN,

MECH DEPT ASSESSMENT COMMENTS:

ROAD TRIP TO WEST POINT

MECH DEPT RESOLUTION COMMENTS:

TIGHTENED LH TRAINLINE AND HOSE

RESOLVED: 05-01-2017 08:37 BY: LPTKE

TT 03-28-2017 FEDERAL INSPECTOR REPORT ITEMS

UNIT TROUBLE COMMENTS:

STARTER COVER NOT PROPERLY SECURED ** EXCESSIVE ACCUMULATION OF OIL ON ELECTRICAL EQUIPMENT, ON #2TM LEADS ** EXCESSIVE ACCUMULATION OF OIL ON AIR COMPRESSOR / TOOL ROOM FLOOR

MECH DEPT RESOLUTION COMMENTS:

CLEANED A/C ROOM CLEANED #2 TRACTION MOTOR LEADS APPLY STARTER COVER R-3 BRAKESHOE OK

RESOLVED: 03-29-2017 14:26 BY: LRM88

TT 03-21-2017 ELECTRICAL WIRING TROUBLE

UNIT TROUBLE COMMENTS:

REPORTED CONTROL FUEL PUMP SWITCH B/O

MECH DEPT RESOLUTION COMMENTS:

REPLACED & SET UP BRAKES

COMPONENT(S) USED:

SWITCH, ENGINE RUN CONTROL & FUEL PUMP

RESOLVED: 03-21-2017 11:03 BY: LRM88

ME 02-01-2017 LIGHTING TROUBLE

UNIT TROUBLE COMMENTS:

LCDI CAT: LIGHTING PROBLEMS, DEF: NUMBER LIGHTS,SHORT HOOD END,

MECH DEPT ASSESSMENT COMMENTS:

INSPECTED UNIT AND FOUND ALL NUMBER LIGHT WORKING AS THEY SHOULD HOWEVER, DURING INSPECTION, LONG HOOD HEADLIGHT HAD ONE LIGHT OUT. FURTHER INSPECTION FOUND A BURNED WIRE ON HEADLI

MECH DEPT RESOLUTION COMMENTS:

REPAIRED BURNT WIRE.

RESOLVED: 02-10-2017 20:08 BY: LR2DD

ME 01-29-2017 CREW CAB TROUBLE

UNIT INFORMATION SHEETS FOR NS 5184 AT SHOP SCY ON 06/20/17 PAGE 4

TASKS AND INFO LISTED ARE VALID THROUGH END OF (ML949A)
SHOPPING COMMENCING ON DATE SHOWN AT TOP OF PAGE

UNIT TROUBLE COMMENTS:

LCDI CAT: CREW CAB PROBLEM , DEF: HEATER TROUBLE,ENG FRONT WALL,AUXILLARY
HEATER ON ENGINEERS SIDE DOES NOT WORK

MECH DEPT RESOLUTION COMMENTS:

REPLACED BRUSHES

COMPONENT(S) USED:

BRUSH, CAB HEATER, SD40-2 LOCOS

RESOLVED: 01-31-2017 23:40 BY: MJT88

BRUSH, CAB HEATER, SD40-2 LOCOS

LAB ANALYSIS HISTORY

	PB	CU	FE	AL	SI	CR	B	ZN	V100	%F	HD	PPI	OS
03-09-2017	10	23	23	2	14	1	3	4	14.9	221	19	43	32

NOTICES DUE

MDH MO 6653 Dash-2 Locomotive Cab Replacement

MDH MO 6839 Replace Toilet Top - Yard/Local Units

JUN SP 4009 Power Assembly User

MDH WR 235 Replace Toilet Floor Flange Seal -Yard/Local Units

UNRESOLVED LAB DATA

HAS NO UNRESOLVED LABS