

UNIT INFORMATION SHEETS FOR NS 5136 AT SHOP SCY ON 04/11/17 PAGE 1

TASKS AND INFO LISTED ARE VALID THROUGH END OF SHOPPING COMMENCING ON DATE SHOWN AT TOP OF PAGE (ML949A)

| CRITICAL UNIT DATA | | | |
|-----------------------------|-----------|------|----------|
| | LAST DONE | SHOP | NEXT DUE |
| # OIL/WTR SAMP | 03/16/17 | STL | 03/30/17 |
| # LUBE | 02/25/17 | SPE | 04/10/17 |
| # 3 MONTH - MAINT EXPEDITED | 02/25/17 | SPE | 03/24/17 |
| # 6 MONTH | 11/23/16 | SPE | 03/24/17 |
| # METER | 05/28/16 | STL | 03/24/17 |
| # 12 MONTH | 05/28/16 | STL | 03/24/17 |
| - 24/36/48/60 | 04/25/15 | CON | 02/27/18 |
| # EVENT RECORDER | 02/25/17 | SPE | 03/24/17 |
| # EPA 1 YEAR | 05/28/16 | STL | 03/24/17 |
| - EPA 3 YEAR | 04/25/15 | CON | 05/02/18 |
| - MID-LIFE TUNE UP | 11/15/11 | JUN | 01/04/18 |
| # OVERHAUL | 01/30/05 | JUN | 04/07/17 |
| # TRUCK CHANGE | 02/07/05 | JUN | 04/12/16 |
| - RETRO REFLECTIVE | 05/28/16 | STL | 06/24/26 |

AIR COMP: ? AIR DRYER: ? OIL CHG: 06/12/13

RI: 89 EPA: 0 RAILVIEW: N APU: ?

CAB SGNL: N TM TYPE: 723D77,40H BEARING TYPE: HYATT RMT CTL: N

| COMPONENT CHANGE HISTORY | | | |
|--------------------------|--|--|-----|
| DATE | DESCRIPTION | | POS |
| 03-09-2017 | BATTERY, LOCO START 510AH UNITIZED EXIDE | | ALL |
| 02-28-2017 | TREATMENT, COOLING WATER. WATER | | N/A |
| 02-28-2017 | TM, COMBO, D77/D77B 40 IN HYATT JRN BRG | | 001 |
| 02-24-2017 | HEAD, BRAKE SHOE, ANGLED 5 DEG CANT | | N/A |
| 02-24-2017 | SHOE, COMPOSITE BRAKE 2IN | | ALL |
| 02-24-2017 | BATTERY, LOCO START 510AH UNITIZED EXIDE | | ALL |
| 02-24-2017 | LOCO SAMPLE BOTTLE W/ LID, PLASTIC | | N/A |
| 02-24-2017 | GASKET COVER FUEL OIL FILTER | | N/A |
| 02-24-2017 | FILTER, LUBE OIL | | N/A |
| 02-24-2017 | ELEMENT, SPIN ON FUEL FILTER | | N/A |
| 02-24-2017 | SHOE, COMPOSITE BRAKE 2IN | | ALL |
| 02-24-2017 | FORM, ME-65 LOCOMOTIVE DAILY INSPECTION | | N/A |
| 11-21-2016 | ELEMENT, FIBERGLASS BAGGY TYPE FILTER | | N/A |
| 11-21-2016 | GASKET COVER LUBE OIL FILTER MICHIANA | | N/A |
| 11-21-2016 | FILTER, LUBE OIL | | ALL |
| 11-21-2016 | GASKET COVER FUEL OIL FILTER | | N/A |
| 11-21-2016 | FILTER, LUBE OIL | | N/A |
| 11-21-2016 | SHOE, COMPOSITE BRAKE 2IN | | ALL |
| 11-21-2016 | ELEMENT, SPIN ON FUEL FILTER | | N/A |
| 11-21-2016 | ELEMENT, AIR COMPRESSOR FILTER, ROUND | | N/A |
| 11-21-2016 | FILTER, APU & AIR COMP LUBE OIL | | N/A |
| 11-21-2016 | SHOE, COMPOSITE BRAKE 2IN | | ALL |
| 11-21-2016 | FORM, ME-65 LOCOMOTIVE DAILY INSPECTION | | ALL |

UNIT INFORMATION SHEETS FOR NS 5136 AT SHOP SCY ON 04/11/17 PAGE 2

TASKS AND INFO LISTED ARE VALID THROUGH END OF SHOPPING COMMENCING ON DATE SHOWN AT TOP OF PAGE (ML949A)

11-21-2016 LOCO SAMPLE BOTTLE W/ LID, PLASTIC N/A

UNSCCHEDULED SHOPPING HISTORY

03-08-2017 CHA ready

LATEST WHEEL DATA

| AXLE | LRT | LFH | LFT | RRT | RFH | RFT |
|------|---------|--------|--------|---------|--------|--------|
| 1 | 1 8/16 | 1 3/16 | 1 5/16 | 1 7/16 | 1 2/16 | 1 4/16 |
| 2 | 2 12/16 | 1 3/16 | 1 6/16 | 2 12/16 | 1 3/16 | 1 6/16 |
| 3 | 1 13/16 | 1 1/16 | 1 6/16 | 1 13/16 | 1 1/16 | 1 6/16 |
| 4 | 2 12/16 | 1 3/16 | 1 6/16 | 2 13/16 | 1 3/16 | 1 6/16 |

KIPS READING > 75

POS PEAK DATE
HAS NO WHEEL DATA AVAILABLE

OPEN ACCIDENTS

HAS NO OPEN ACCIDENTS

TROUBLE HISTORY

ME 03-30-2017 CREW CAB TROUBLE
 UNIT TROUBLE COMMENTS:
 LCDI CAT: CREW CAB PROBLEM , DEF: SEAL MISSING/BROKEN,OTHER,UNIT DEAD IN
 TOM OFF BELL. PIT WAS GOLD CARDED BY THEIR FORCES
 RESOLVED: BY:

TT 03-20-2017 STORE UNIT
 UNIT TROUBLE COMMENTS:
 CONTACT SOC ON ARRIVAL AT SHOP TO HAVE UNIT PLACED IN STORED STATUS.
 MECH DEPT ASSESSMENT COMMENTS:
 CONTACTED SOC UPON ARRIVAL
 MECH DEPT RESOLUTION COMMENTS:
 UNIT PLACED IN STORED STATUS
 RESOLVED: 04-01-2017 11:20 BY: HTYGG

ME 03-08-2017 WILL NOT START OR RUN/BATTERY
 UNIT TROUBLE COMMENTS:
 LCDI CAT: STARTING /SHUTDOWN, DEF: ENG WILL NOT START,BATTERIES DEAD/WEAK,
 MECH DEPT RESOLUTION COMMENTS:
 RENEWED BOTH BATTERIES. STARTING OK.
 COMPONENT(S) USED:
 BATTERY, LOCO START 510AH UNITIZED EXIDE
 RESOLVED: 03-09-2017 11:47 BY: MBQIF

TT 02-27-2017 WHEEL TRUE/ WHEEL TROUBLE

UNIT INFORMATION SHEETS FOR NS 5136 AT SHOP SCY ON 04/11/17 PAGE 3

TASKS AND INFO LISTED ARE VALID THROUGH END OF SHOPPING COMMENCING ON DATE SHOWN AT TOP OF PAGE (ML949A)

UNIT TROUBLE COMMENTS:

NEEDS WHEEL TRUE SEE REPORT

MECH DEPT RESOLUTION COMMENTS:

TRUED WHEELS

COMPONENT(S) USED:

TM, COMBO, D77/D77B 40 IN HYATT JRN BRG
RESOLVED: 02-28-2017 14:08 BY: MDCTC

TT 02-10-2017 CARBODY TROUBLE

UNIT TROUBLE COMMENTS:

STRUCK TREE HANDRAIL DAMAGE

MECH DEPT RESOLUTION COMMENTS:

REPAIRED HANDRAIL

RESOLVED: 02-11-2017 00:46 BY: JXW2X
TM, COMBO, D77/D77B 40 IN HYATT JRN BRG

LAB ANALYSIS HISTORY

| | PB | CU | FE | AL | SI | CR | B | ZN | V100 | %F | HD | PPI | OS |
|------------|----|----|----|----|----|----|---|----|------|-----|----|-----|----|
| 03-16-2017 | 10 | 11 | 2 | 2 | 1 | 1 | 1 | 1 | 13.2 | 212 | 12 | 37 | 26 |
| 02-28-2017 | 1 | 9 | 10 | 1 | 4 | 1 | 1 | 1 | 13.3 | 220 | 16 | 36 | 25 |
| 02-24-2017 | 1 | 9 | 9 | 1 | 3 | 1 | 1 | 1 | 13.3 | 221 | 16 | 36 | 25 |
| 11-20-2016 | 2 | 15 | 14 | 2 | 4 | 2 | 2 | 1 | 12.9 | 212 | 15 | 48 | 25 |
| 11-03-2016 | 3 | 16 | 14 | 2 | 5 | 2 | 2 | 1 | 12.7 | 221 | 16 | 56 | 27 |
| 10-09-2016 | 3 | 15 | 16 | 2 | 9 | 2 | 2 | 2 | 12.7 | 221 | 17 | 52 | 25 |

NOTICES DUE

MDH MO 6653 Dash-2 Locomotive Cab Replacement

MDH MO 6727 Dash 2 Battery Saver ZTR

UNRESOLVED LAB DATA

03-16-2017: ADD 4 GALS OR 4 POUCHES OR 24 BAGS OF BORON TREATMENT.
SYSTEM: COOLING