

UNIT INFORMATION SHEETS FOR NS 5162 AT SHOP SCY ON 02/11/16 PAGE 1

TASKS AND INFO LISTED ARE VALID THROUGH END OF SHOPPING COMMENCING ON DATE SHOWN AT TOP OF PAGE (ML949A)

CRITICAL UNIT DATA			
	LAST DONE	SHOP	NEXT DUE
# LUBE	12/05/15	SPE	01/18/16
- 3 MONTH - MAINT EXPEDITED	12/05/15	SPE	03/05/16
- 6 MONTH	12/05/15	SPE	06/02/16
- METER	06/01/15	SPE	06/02/16
- 12 MONTH	06/01/15	SPE	06/02/16
- 24/36/48/60	06/01/15	SPE	06/08/18
- EVENT RECORDER	12/05/15	SPE	03/05/16
- EPA 1 YEAR	06/01/15	SPE	06/02/16
- EPA 3 YEAR	06/01/15	SPE	06/08/18
- MID-LIFE TUNE UP	11/10/11	JUN	01/12/18
- OVERHAUL	07/13/04	JUN	07/17/16
# TRUCK CHANGE	05/27/03	JUN	08/12/14
- RETRO REFLECTIVE	06/13/06	CHA	06/02/16
- BATTERY SET CHANGE	07/16/15	SCX	08/11/25

AIR COMP: 07/04/04 AIR DRYER: ? OIL CHG: ?
 RI: EPA: 0 RAILVIEW: N APU: ?
 CAB SGNL: N TM TYPE: 723D77,40H BEARING TYPE: HYATT RMT CTL: N

COMPONENT CHANGE HISTORY			
DATE	DESCRIPTION		POS
12-05-2015	FILTER, LUBE OIL		N/A
12-05-2015	GASKET COVER LUBE OIL FILTER MICHIANA		N/A
12-05-2015	MOTOR, STARTER, 32VDC		N/A
12-05-2015	SHAFT, 5-1/4 IN AXLE ALTERNATOR DRIVE		004
12-05-2015	SPRING, HANDBRAKE, HOLDING PAWL, TENSION		N/A
12-05-2015	ELEMENT, FIBERGLASS BAGGY TYPE FILTER		N/A
12-05-2015	GASKET COVER FUEL OIL FILTER		N/A
12-05-2015	FILTER, LUBE OIL		N/A
12-05-2015	SHOE, COMPOSITE BRAKE 2IN		ALL
12-05-2015	ELEMENT, SPIN ON FUEL FILTER		N/A
12-05-2015	ELEMENT, AIR COMPRESSOR FILTER, ROUND		N/A
12-05-2015	FILTER, APU & AIR COMP LUBE OIL		N/A
12-05-2015	BOTTLE, PLASTIC 4 OZ, 525 IN A CASE		N/A
12-05-2015	SHOE, COMPOSITE BRAKE 2IN		ALL
12-05-2015	LUBRICANT, SODIUM BASE 1LB		ALL
12-05-2015	LAMP, 50W 75V A19 MED BASE INSIDE FROST		N/A
12-05-2015	FORM, ME-65 LOCOMOTIVE DAILY INSPECTION		N/A
12-05-2015	SWITCH, EMD 8298178 ROLLER BUTTON		N/A
12-05-2015	SWITCH, ROLLER BUTTON EMD		N/A
12-05-2015	SWITCH, EMD 8296750 ROLLER		N/A
12-05-2015	SWITCH, ROLLER BUTTON		N/A
10-21-2015	LAMP, DITCH/HEADLIGHT HALOGEN 75V 350W		F
10-21-2015	RESISTOR, 8 OHM, 400 WATT HEADLIGHT		N/A

UNIT INFORMATION SHEETS FOR NS 5162 AT SHOP SCY ON 02/11/16 PAGE 2

TASKS AND INFO LISTED ARE VALID THROUGH END OF SHOPPING COMMENCING ON DATE SHOWN AT TOP OF PAGE (ML949A)

09-09-2015	ALTERNATOR, AXLE, KIT, 20 PULSES PER REV	L01
09-04-2015	GASKET COVER FUEL OIL FILTER	N/A
09-04-2015	FILTER, LUBE OIL	N/A
09-04-2015	ELEMENT, SPIN ON FUEL FILTER	N/A
09-04-2015	SHOE, COMPOSITE BRAKE 2IN	ALL
09-04-2015	LUBRICANT, SODIUM BASE 1LB	ALL
09-04-2015	SHOE, COMPOSITE BRAKE 2IN	ALL
09-04-2015	LUBRICANT, SODIUM BASE 1LB	ALL
09-04-2015	MOTOR, EMD WINDOW WIPER W/GUARD	N/A
09-04-2015	TRAP, SAND, ROTARY MANUAL SHUTOFF	SH
09-04-2015	BOTTLE, PLASTIC 4 OZ, 525 IN A CASE	N/A
09-04-2015	FORM, ME-65 LOCOMOTIVE DAILY INSPECTION	N/A
09-04-2015	LAMP, 25W 34V A19 MED BASE FOR LOCO	N/A
09-04-2015	LAMP, DITCH/HEADLIGHT HALOGEN 75V 350W	SH
09-04-2015	GLOBE GLASS LIGHT FIXTURE CLEAR	N/A

UNSCCHEDULED SHOPPING HISTORY

10-20-2015 SPE
09-08-2015 SPE

LATEST WHEEL DATA

AXLE	LRT	LFH	LFT	RRT	RFH	RFT
1	1 6/16	1 5/16	1 6/16	1 6/16	1 4/16	1 5/16
2	2 8/16	1 5/16	1 4/16	2 9/16	1 5/16	1 8/16
3	1 15/16	1 3/16	1 5/16	1 14/16	1 4/16	1 4/16
4	2 6/16	1 4/16	1 6/16	2 8/16	1 4/16	1 7/16

KIPS READING > 75

POS PEAK DATE
HAS NO WHEEL DATA AVAILABLE

OPEN ACCIDENTS

HAS NO OPEN ACCIDENTS

TROUBLE HISTORY

TT 12-16-2015 STORE UNIT
UNIT TROUBLE COMMENTS:
CONTACT SOC UPON ARRIVAL AT SHOP TO BE PLACED IN STORED STATUS. UNIT SHOULD BE STORED AT THE FOLLOWING LOCATION:
MECH DEPT ASSESSMENT COMMENTS:
NEED FOR POWER
RESOLVED: BY:

TT 11-18-2015 SPEED INDICATOR TROUBLE (LDI 1)
UNIT TROUBLE COMMENTS:

UNIT INFORMATION SHEETS FOR NS 5162 AT SHOP SCY ON 02/11/16 PAGE 3

TASKS AND INFO LISTED ARE VALID THROUGH END OF (ML949A)
 SHOPPING COMMENCING ON DATE SHOWN AT TOP OF PAGE

CREW CAB PROBLEM
 LCDI CAT: SPEEDOMETER, DEF: ERRATIC,CONTROL STAND,ERRATIC BELOW 10 MPH,
 ESP. LONG HOOD FORWARD
 MECH DEPT ASSESSMENT COMMENTS:
 SPEEDO ERRATIC .

MECH DEPT RESOLUTION COMMENTS:
 CHECKED SPEEDO WITH TEST BOX, TESTED GOOD. REMOVED AXLE ALT. FOUND
 PADDLE WAS TO SHORT , NOT MAKING CONTACT. REPLACED WITH PROPER PADDLE ,
 TRACK TESTED , WORKS AS INTENDED.

COMPONENT(S) USED:
 AXLE ALT.DRIVE PADDLE
 RESOLVED: 12-05-2015 11:54 BY: MBN0C

ME 11-09-2015 ALERTOR / CREW CALL
 UNIT TROUBLE COMMENTS:
 LCDI CAT: CREW CAB PROBLEM , DEF: ALERTNESS DEVICE,OTHER,CYCLE TIME TOO
 SHORT - 22 SEC. AT ANY SPEED

MECH DEPT RESOLUTION COMMENTS:
 CHECKED ALERTER. WORKS AS INTENDED. FROM TIME OF HITTING THE SWITCH TO A
 PENALTY BRAKE APPLICATION WAS 42 SECONDS. WORKS AS INTENDED.
 RESOLVED: 12-05-2015 11:57 BY: MBN0C

TT 10-19-2015 LIGHTING TROUBLE
 UNIT TROUBLE COMMENTS:
 MECH.RPTD. HEADLIGHT TROUBLE. B/O RESISTOR ON S/H END AND WIRES BURNT OFF
 RESISTOR ON L/H END.(WJ)

MECH DEPT ASSESSMENT COMMENTS:
 FOUND HEADLIGHT RESISTOR B/O
 MECH DEPT RESOLUTION COMMENTS:
 REPLACED HEADLIGHT RESISTOR AND TWO HEADLIGHTS CHECKED OK

COMPONENT(S) USED:
 RESISTOR
 LIGHTBULB,HEADLIGHT
 RESOLVED: 10-21-2015 01:50 BY: MT9QX

TT 09-08-2015 SPEED INDICATOR TROUBLE (LDI 1
 UNIT TROUBLE COMMENTS:
 LCDI CAT: SPEEDOMETER, DEF: ERRATIC,CONTROL STAND,ERRATIC FROM 1 TO 7
 MILES PER HOUR.

MECH DEPT ASSESSMENT COMMENTS:
 FOUND AXLE ALT. WORN OUT..
 MECH DEPT RESOLUTION COMMENTS:
 REPLACED AXLE ALT..TRACK TESTED BETWEEN 1 AND 7 MPH..TRACK TESTED GOOD..NO
 FLUCTUATION

COMPONENT(S) USED:
 AXLE ALTERNATOR
 RESOLVED: 09-09-2015 10:28 BY: MUE96
 AXLE ALTERNATOR

LAB ANALYSIS HISTORY

	PB	CU	FE	AL	SI	CR	B	ZN	V100	%F	HD	PPI	OS
01-01-2016		6	11	1	5	2		1	14.9	223	15	35	26

UNIT INFORMATION SHEETS FOR NS 5162 AT SHOP SCY ON 02/11/16 PAGE 4

TASKS AND INFO LISTED ARE VALID THROUGH END OF (ML949A)
SHOPPING COMMENCING ON DATE SHOWN AT TOP OF PAGE

12-05-2015	6	14	2	5	3	1	1	15.0	222	16	36	27
10-21-2015	3	8	1	5	1	1	1	14.6	223	16	33	25
09-21-2015	3	5	8	1	4	2		14.6	223	17	35	23
09-04-2015	4	6	14		4	4		14.0	222	27	43	25

NOTICES DUE

- MDH MO 6653 Dash-2 Locomotive Cab Replacement
- MDH MO 6727 Dash 2 Battery Saver ZTR
- MDH MO 6821 Remove Exterior Toilet Dump Slide Valve
- MDH MO 6825 Replace toilet top
- JUN SP 2222 TEST LINERS MICRO PROFILE
- MDH WR 221 Replace Toilet Floor Flange Seal
- MDH WR 222 Apply Toilet Chemical Sticker to Toilet

UNRESOLVED LAB DATA

HAS NO UNRESOLVED LABS